

RECEIVED

585-9E-33ac

STATE OF OREGON WATER-WELL REPORT (as required by ORS 537.765)

Klam 10351

NOV 14 1991

(START CARD) # 917062

(1) OWNER: Name CHURCH OF JESUS CHRIST OF LATTER DAY SAINTS, Address 3095 ELDER STREET - SUITE 350, City BOISE, State IDAHO, Zip 83705

(2) TYPE OF WORK: [X] New Well [ ] Deepen [ ] Recondition [ ] Abandon

(3) DRILL METHOD: [ ] Rotary Air [X] Rotary Mud [ ] Cable [ ] Other

(4) PROPOSED USE: [ ] Domestic [ ] Community [ ] Industrial [ ] Irrigation [ ] Thermal [X] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No, Depth of Completed Well 756 ft., Explosives used [ ] [X] Type Amount

Table with columns: HOLE Diameter, SEAL Material, Amount sacks or pounds. Includes entries for 12 1/4 inch diameter cement seal from 0 to 240 feet (95 sacks) and 7 1/2 inch diameter seal from 240 to 756 feet.

How was seal placed: Method [ ] A [ ] B [ ] C [X] D [ ] E, Backfill placed from ft. to ft., Material, Gravel placed from ft. to ft., Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Includes entry for 8 5/8 inch casing from 0 to 240 feet.

Final location of shoe(s) 240 FEET

(7) PERFORATIONS/SCREENS: [ ] Perforations Method, [ ] Screens Type Material

Table for Perforations/Screens with columns: From, To, Slot size, Number, Diameter, Telo/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour. [ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian. Yield gal/min 150, Drawdown, Drill stem at 240, Time 1 hr.

Temperature of water 172°F, Depth Artesian Flow Found, Was a water analysis done? [ ] Yes [ ] No, Did any strata contain water not suitable for intended use? [ ] Too little [ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other, Depth of strata:

(9) LOCATION OF WELL by legal description: County KLAMATH, Latitude, Longitude, Township 38S, Nor S. Range 9E, E or W, WM, Section 33 SW 1/4 NE 1/4, Tax Lot, Lot, Block, Subdivision, Street Address of Well (or nearest address) HOME OF MARTIN ST., KLAMATH FALLS, OREGON 97601

(10) STATIC WATER LEVEL: 9 ft. below land surface, Date 10/16/91, Artesian pressure lb. per square inch, Date

(11) WATER BEARING ZONES: Table with columns: From, To, Estimated Flow Rate, SWL. Depth at which water was first found INDETERMINATE.

(12) WELL LOG: Table with columns: Material, From, To, SWL. Includes entries for ASPHALT & GRAVEL, BROWN CLAY, YELLOW CLAY, GREEN CLAY, STICKY GREY CLAY, STICKY BROWN CLAY & ASH, HARD BROWN ASH, BROWN CLAY & ASH, BLACK SHALE, HARD BLACK ASH, HARD BROWN GREY BASALT, HARD BROWN BLACK BASALT, BLACK ASH WITH STRONG GREY CLAY, BLACK BASALT WITH STRONG GREY CLAY, HARD BROWN BLACK BASALT, HARD GREY BASALT, BROWN BLACK BASALT, HARD BROWN GREY BASALT, HARD BLACK BASALT, GREY ASH.

Date started 9/27/91 Completed 10/16/91

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number, Signed, Date

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief. WWC Number 601, Signed, Date 11/10/91