17

KLAM 10431

RECEIVED MAR 31 1992

39S/11E/16da

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

(START CARD) # 29003

(1) OWNER:
Well Number: 3
Name: BONANZA VIEW DAIRY
Address: 4721 HARPOLD RD.
City: BONANZA, State: OR Zip: 97623

(2) TYPE OF WORK:
X New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD
X Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial X Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No X Depth of Completed Well 104' ft.
Explosives used Yes ☐ No ☐ Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
20"	0	19'	CEMENT	0	19	10sac.
16'	19'	90	OPEN			
10"	90'	104	OPEN			

How was seal placed: Method ☐ A ☐ B X C ☐ D ☐ E
☐ Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	16"	+1	19'.	250	X	☐	X	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	NONE				☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) 21'

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer X Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
4500		27'	1 hr.

Temperature of water 61 Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other NONE
Depth of strata:

(9) LOCATION OF WELL by legal description:
County KLAMATH Latitude Longitude
Township 39 S N or S. Range 11 EAST E or W. WM.
Section 16 NE ¼ SE ¼
Tax Lot 2800 Lot Block Subdivision
Street Address of Well (or nearest address) 4700 HAROLD RD
BONANZA, OR.

(10) STATIC WATER LEVEL:
24' ft. below land surface. Date 3, 20, 92
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 25'

From	To	Estimated Flow Rate	SWL
25	45	50 GPM	24'
45	53	20 GPM	24'
53	62	200 GPM	24'
62	104	4300GPM	24'

(12) WELL LOG:
Ground elevation 4150

Material	From	To	SWL
TOP SOIL	0	1	
YELLOW CLAYSTONE	1	6	
BLK & BRN LAVA ROCK	6	45	24
BROKEN BROWN ROCK	45	53	24
BROKEN BALCK ROCK	53	62	24
BUBBLY BROWN LAVA	62	104	24

Date started 3, 5, 92 Completed 3, 26, 92

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 408
Signed Nancy Seely Date

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88