ORIGINAL
File Original, and Duplicate with the STATE ENGINEER, SALEM, OREGON

RECEIVED OCT 31 1957 STATE ENGINEER SALEM, OREGON

WATER WELL DRILLERS REPORT
STATE OF OREGON

G698

Do Not Fill In
State Well No. 29/9-5 K (1)
State Permit No. G-615

(1) OWNER:
Name Weyerhaeuser Timber Co.
Address Klamath Falls, Ore

(2) LOCATION OF WELL:
County Klamath Owner's number, if any— 2
R. F. D. or Street No.
Bearing and distance from section or subdivision corner
S. 87°20'E dist. 2872 from West 1/4 corner S. 5, T. 29S., R. 9E., W.M.

(3) TYPE OF WORK (check):
New well ☑ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☑ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) EQUIPMENT:
Rotary ☐
Cable ☑
Dug Well ☐

CASING INSTALLED:
Threaded ☐ Welded ☑

FROM	ft. to	ft.	Diam.	Gage or Wall
0"	" 370	"	"	.188"
"	"	"	"	"
"	"	"	"	"
"	"	"	"	"
"	"	"	"	"

If gravel packed

Diameter of Bore	from ft.	to ft.
	"	"
	"	"
	"	"
	"	"
	"	"

Type and size of shoe or well ring W-6
Size of gravel:
Describe joint Stainless Steel

(7) PERFORATIONS:
Type of perforator used
SIZE of perforations 1/4 in., length, by 4 in.

FROM	ft. to	ft.	perf per foot	No. of rows
330	370		2	6
"	"	"	" " "	" " "
"	"	"	" " "	" " "
"	"	"	" " "	" " "
"	"	"	" " "	" " "

SCREENS:
Give Manufacturer's Name, Model No. and Size

(8) CONSTRUCTION:
Was a surface sanitary seal provided? ☑ Yes ☐ No To what depth ft.
Were any strata sealed against pollution? ☐ Yes ☑ No
If yes, note depth of strata

FROM	ft. to	ft.
"	"	"

METHOD OF SEALING

(9) WATER LEVELS:
Depth at which water was first found 360 ft.
Standing level before perforating 340 ft.
Standing level after perforating 340 ft.

Log Accepted by:
[Signed] W.T.Co. Owner
Dated Sept. 19, 1957
G. W. Wamington
Const. Supt.

(10) WELL TESTS:
KLAM 11773

Was a pump test made? ☑ Yes ☐ No If yes, by whom?

Yield:	gal./min. with	ft. draw down after	hrs.
250	" None	"	3"
"	"	"	"

Artesian flow ..... g.p.m.
Shut-in pressure ..... lbs. per square inch.
Bailer test ..... g.p.m. with ..... ft. drawdown
Temperature of water Was a chemical analysis made? ☐ Yes ☐ No
Was electric log made of well? ☑ Yes ☐ No

(11) WELL LOG:
Diameter of well, 8 inches.
Total depth 380 ft. Depth of completed well 380 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

ft. to	ft.	
0"	17	pumice
17	90"	rock and clay
90"	118	lava rock
118"	290"	rock and clay
290"	310"	lava rock
310"	360"	burnt lava
360"	380"	lava rock

Ground elevation at well site 4450 feet above mean sea level.
Work started Aug 1957 Completed Sept. 1957

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME W. L. Hartley & Son (Person, firm, or corporation) (Typed or printed)
Address Bonanza Oregon
Driller's well number
[Signed] Robert F. Hartley (Well Driller)
License No. 114 Dated Sept. 16, 1957