

NOTICE TO WATER WELL CONTRACTOR

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED
AUG 7 1970

WATER WELL REPORT

STATE ENGINEER OF OREGON
SALEM, OREGON (Please type or print)

KLAM
12348

State Well No. 38/11-19ac

State Permit No.

(1) OWNER:

Name EARL EDWARDS
Address STAR RT. BONANZA ORE.

(2) LOCATION OF WELL:

County KLAMATH Driller's well number
SW 1/4 NE 1/4 Section 19 T. 38S R. 11E W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
Abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐ Rotary ☐ Driven ☐
Irrigation ☐ Test Well ☐ Other ☐ Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(5) TYPE OF WELL:

(6) CASING INSTALLED:

10" Diam. from 1" ft. to 61" ft. Gage 114
" Diam. from " ft. to " ft. Gage 250
" Diam. from " ft. to " ft. Gage

(7) PERFORATIONS:

Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.
perforations from " ft. to " ft.
perforations from " ft. to " ft.
perforations from " ft. to " ft.
perforations from " ft. to " ft.
perforations from " ft. to " ft.

(8) SCREENS:

Well screen installed? ☐ Yes ☒ No

Manufacturer's Name
Type Model No.
Slot size Set from " ft. to " ft.
Diam. Slot size Set from " ft. to " ft.

(9) CONSTRUCTION:

Well seal—Material used in seal CEMENT & COM. CLAY
Depth of seal 61 ft. Was a packer used? NO
Diameter of well bore to bottom of seal 12 in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☒ Yes ☐ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from " ft. to " ft.
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? depth of strata
Method of sealing strata off

(10) WATER LEVELS:

Static level 100 ft. below land surface Date MAY 4/70
Artesian pressure lbs. per square inch Date

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☒ Yes ☐ No If yes, by whom? DRILLER
Yield: 60 gal./min. with 9 ft. drawdown after 2 hrs.
"PUMP TEST MADE" SO NO
"BAILER TEST MADE" "
Bailer test gal./min. with " ft. drawdown after " hrs.
Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:

Diameter of well below casing 10"

Depth drilled 130 ft. Depth of completed well 130 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
SANDY LOAM	9	1
SURFACE BOULDERS	1	2
YELLOW SHALE	2	38
WAXY ROCK	38	71
GREY LOAM ROCK	71	93
BROWN WAXY ROCK	93	98
BLACK BASALT BOULDERS	98	104
BLUE BASALT BOULDERS	104	126
BROKEN WAXY ROCK	126	130
WATER BEARING	100	130

Work started 4/15 19 70 Completed 5/14 19 70
Date well drilling machine moved off of well 5/6 19 70

(13) PUMP:

Manufacturer's Name DORWOOD
Type: SUB. H.P. 3

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME CHARLES E. HARTLEY
(Person, firm or corporation) (Type or print)

Address 4579 1/2 56th

Drilling Machine Operator's License No. 233

[Signed] Charles E. Hartley
(Water Well Contractor)

Contractor's License No. 145 Date _____, 19____