## STATE OF OREGON

OCT 12 1989 KLAM 2538

## WATER WELL REPORT

		and the same street & & C	TART CARD) #		
	ALEM, OH	(9) LOCATION	OF WELL by le	egal descripti	ion:
Name City of Klamath Falls		County Klame	Latitude N or S, Range	Longitude	P W WM
Address P.O. Box 237  City Klamath Falls. State OR. Zip	97601	Township	N or S, Range NE	SM	_E OF W, WIVI.
	77001	Section	Bloc		S. Lennox
(2) TYPE OF WORK:	Ì	Tax Lot	ell (or nearest address)	4047 Balsa	m Drive
New Well Deepen Recondition A Abandon		Klamath Fal	1s. Oregon	97601	
(3) DRILL METHOD	į				
Rotary Air Rotary Mud Cable		(10) STATIC W		ı <b>:</b>	9,13,89
Other Abandon		Abandon ft.			
(4) PROPOSED USE:	Artesian pressure lb. per square inch. Date				
☐ Domestic     Community ☐ Industrial ☐ Irrigation		(11) WATER B	EARING ZONI	ES:	
☐ Thermal ☐ Injection ☐ Other		Depth at which water was	first found		
(5) BORE HOLE CONSTRUCTION:		From To Estimated Flow Rate SWL			
Special Construction approval Yes No Depth of Completed Well Yes No	т.	110111			
Explosives used Type Amount	<u> </u>	Abandon			
•	Amount				
Diameter From To Material From To sach	s or pounds				
Abandon:		(12) WELL LO	G: Ground eleva	tion 420	00
10" 0 100 cement 100 0' 4	8 sacks	(,	OTOURA Eleva	From	To SWL
		ADAMON	Material	From	10 541
How was seal placed: Method A B C D E		ABANDON			
Other Inside of casing was filled with	cement.	Casing was r	Inned From 40	)' up to 3 '	t. Then
		the casing was r			
Backfill placed fromft. to ft. Material Gravel placed from 15t. to ft. Size of gravel 3/8	11	Cire Casting Wi	ao bembea ray	77.07.0	
(6) CASING/LINER:					
Diameter From To Gauge Steel Plastic Welde	d Threaded				
Casing: none installed.					
					1
Liner: none					
	Ц				
Final location of shoe(s)					
(7) PERFORATIONS/SCREENS:					
Perforations Method					
Slot Tele/pipe From To size Number Diameter size Casi:	ng Liner				
Abandon	□ -				
		0.1	2 90	0 1	3,89
		Date started 9,1	2,89 <sub>Co</sub>	mpleted9,1	<del></del>
			Well Constructor C		
(8) WELL TESTS: Minimum testing time is 1 hou	owing	I certify that the	ne work I performed	on the constructi	on, alteration, o
☐ Pump ☐ Bailer ☐ Air ☐ Ai	tesian	standards. Materials	used and information	n reported above a	re true to my bes
Yield gal/min Drawdown Drill stem at	Time	knowledge and belief.		******	1
No test ABANDON	1 hr.	Signed Date			
IIV LEGO		Signed		Date	
		1 .	ell Constructor Cer		
I accept responsibility for the construction, alteration, or abandonme work performed on this well during the construction dates reported above.					
Was a water analysis done? Yes By whom work performed during this time is in					rith Oregon we
Did any strata contain water not suitable for intended use?   Too little	construction standar	ds. This report is tru	ue to the best of n	ny knowledge an	
Salty Muddy Odor Colored Other				WWC No	mber <u>408</u>
Depth of strata: Abandon	Signed	m sury	Date	10,8,89	