

RECEIVED
AUG 15 1960
STATE ENGINEER

WATER WELL REPORT
STATE OF OREGON

KLAM
2040

State Well No. 3612-4R(1)
State Permit No.

File Original and
First Copy with the
STATE ENGINEER,
SALEM, OREGON

(1) OWNER:

Name Mrs Alice Miller
Address Beatty, Oregon

(2) LOCATION OF WELL:

County Klamath Owner's number, if any—
1/4 Section T. R. W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

New Well Deepening Reconditioning Abandon
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic Industrial Municipal
Irrigation Test Well Other

(5) TYPE OF WELL:

Rotary Driven
Cable Jetted
Dug Bored

(6) CASING INSTALLED:

Threaded Welded
" Diam. from 0 ft. to 2-80 ft. Gage 250
" Diam. from _____ ft. to _____ ft. Gage _____
" Diam. from _____ ft. to _____ ft. Gage _____

(7) PERFORATIONS:

Perforated? Yes No
Type of perforator used _____
SIZE of perforations in. by in.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.

(8) SCREENS:

Well screen installed Yes No
Manufacturer's Name _____
Type _____ Model No. _____
Diam. Slot size Set from _____ ft. to _____ ft.
Slot size Set from _____ ft. to _____ ft.

(9) CONSTRUCTION:

Was well gravel packed? Yes No Size of gravel: _____
Gravel placed from _____ ft. to _____ ft.
Was a surface seal provided? Yes No To what depth? _____ ft.
Material used in seal— Cement
Did any strata contain unusable water? Yes No
Type of water? _____ Depth of strata 180
Method of sealing strata off _____

(10) WATER LEVELS:

Static level _____ ft. below land surface Date _____
Artesian pressure 17 lbs. per square inch Date _____

Log Accepted by:

[Signed] _____ Date _____, 19____
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level
Was a pump test made? Yes No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " " "
" " " " "
" " " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow 650 g.p.m. Date Aug 1960
Temperature of water _____ Was a chemical analysis made? Yes No

(12) WELL LOG:

Diameter of well 8 inches.
Depth drilled 612 ft. Depth of completed well 612 ft.
Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
<u>Current gravel</u>	<u>0</u>	<u>17</u>
<u>Chalk</u>	<u>17</u>	<u>220</u>
<u>black sand</u>	<u>220</u>	<u>280</u>
<u>Chalk</u>	<u>280</u>	<u>612</u>
<u>artesian flow</u>		
<u>come in</u>		
<u>black sand and</u>		
<u>pebbles</u>		

Work started 19 _____ Completed 19 _____

(13) PUMP:

Manufacturer's Name _____
Type: _____ H.P. _____

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME W.S. Hartley & Sons
(Person, firm, or corporation) (Type or print)

Address Bonanza Dr

Driller's well number _____

[Signed] Robert Z Hartley
(Well Driller)

License No. 164 Date Aug 9, 1960
Well drilled for house in 1954