STATE OF OREGON

(as required by ORS 537.765)

(START CARD) ***58269**

KLAN, 298 KECEIVED WATER SUPPLY WELL REPORT

Instructions for completing this report are on the last page of this WATER RESOURCES DEPT. Well Number LO1121 SALEM, OREGON (9) LOCATION OF WELL by legal description: Name OREGON SHORES BEACH CLUB, County KLAMATH Latitude Longitude Address 3800 MODOC POINT RD. Township 35 S N or S Range 07 E Zip 97624 1/4 SW Section O6 DA NE City CHILOQUIN 1/4 Tax Lot **4400** Subdivision Block (2) TYPE OF WORK Street Address of Well (or nearest address) 2924 SHORE VIEW New Well Deepening Alteration (repair/recondition) Abandonment CHILOQUIN, OR DRIVE. (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Air Rotary Mud Cable Auger Date 06-05-96 98 FT. ft. below land surface. Other 1b. per square inch. (4) PROPOSED USE: Artesian pressure (11) WATER BEARING ZONES: Industrial Community Irrigation Domestic Injection Livestock Other Thermal Depth at which water was first found NO ADDITIONAL (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes M No Depth of Completed Well 535 ft. SWL То Estimated Flow Rate Explosives used Yes No Type From SEAL HOLE Sacks or pounds Diameter Material From To 400 484 **50 SKS** 0 535 CEMT. 10" (12) WELL LOG: □ E Ground Elevation 4150 How was seal placed: Method \square A Other _ SWI To Material From Backfill placed from Material ft. to NO DRILLING PERFORMED Size of gravel Gravel placed from ft. to CLEANED WELL & PUT IN (6) CASING/LINER: CASING & CEMENT Plastic Welded Threaded To Gauge Steel Diameter Casing 8 Liner: NONE Final location of shoe(s) 484 FT (7) PERFORATIONS/SCREENS: Perforations Method NONE Material Screens Type Tele/pipe Diameter Casing Liner Number From Completed 06-05-96 Date started 05-24-96 (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment X Air Artesian Bailer Pump of this well is in compliance with Oregon water supply well construction standards. Time Materials used and information reported above are true to the best of my knowledge Drill stem at Drawdown Yield gal/min 1 hr. and belief. 250 FT. 300 WWC Number Date (bonded) Water Well Constructor Certification: Depth Artesian Flow FoundNONE Temperature of water 59 F I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Salty Muddy Odor Colored Other WWC Number 408 Depth of strata: NONE Date 6-7-90 ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER