

RECEIVED
KLAM 51979
SEP 15 1999

WATER RESOURCES DEPT.
SALEM, OREGON

(1) OWNER: **DEAN AND GERRI SCHNECK** Well Number
 Name **36588 MODOC POINT RD.**
 Address
 City **CHILOQUIN,** State **OR** Zip **97624**
 ABANDON

(3) DRILL METHOD: ☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other

(4) PROPOSED USE:

☒ Domestic	☐ Community	☐ Industrial	☐ Irrigation
☐ Thermal	☐ Injection	☐ Livestock	☐ Other ABANDON

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☒ Yes ☐ No Depth of Completed Well _____ ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	
6"	-4	66	BENTONITE	-65	-9	15 SACK
6"	-4	66	CEMENT	-9	-4	1 SACK

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other **POURED**

Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) **UNKNOWN**

(7) PERFORATIONS/SCREENS:

☐ Perforations Method _____
☐ Screens Type _____ Material _____
 Tele/pipe size _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Line
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump	☐ Bailer	☐ Air	☐ Flowing ☐ Artesian
Yield gal/min	Drawdown	Drill stem at	Time
NONE	ABANDON		1 hr.

Temperature of water _____ Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other **ABANDON**

Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County **KLAMATH** Latitude _____ Longitude _____
Township **35 S** N or S Range **07 E** E or W. WM.
Section **07** **NE** 1/4 **NW** 1/4
Tax Lot **1300** Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) **36588 MODOC PT. RD**
CHILOQUIN, OR. 97624

(10) **STATIC WATER LEVEL:**
NONE ft. below land surface. Date **ABANDON**
 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found **ABANDON**

From	To	Estimated Flow Rate	SWL
		ABANDONMENT	

(12) WELL LOG: Ground Elevation 4150

Material	From	To	SWL
ABANDONMENT			
FILLED WITH 3/8" BENTONITE			
FROM BOTTOM OF WELL	(66)		
UP TO -9'. A 5' CEMENT CAP			
WAS PUT ON TOP OF THE			
BENTONITE FILL.			
THIS WELL WAS IN A PIT IT			
COULD NOT BE ACCESSED WITH A			
RIG. SPECIAL STANDARDS WERE GIVEN			
FOR THIS ABANDONMENT.			
THE REMAINING PIT WAS CLEANED OF			
ALL DEBRIS. THEN FILLED WITH			
DIRT ONLY TO THE LEVEL OF THE			
GROUND.			

Date started 09/07/99 Completed 09/07/99
(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number +1560
Signed J. Brett Pinkard Date 9-14-99

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Norm Leven WWC Number 408
Date _____