

STATE OF OREGON
WATER WELL REPORT
 (as required by ORS 537765)

KLAM 53251
 53251

WELL ID # L46028
 (START CARD) # 108737

(1) OWNER 02 09
 COWAN ENTERPRISES
 7647 LIBBY RD. NE
 OLYMPIA, WA 98506

(2) TYPE OF WORK : DEEPEN

(3) DRILL METHOD : ROTARY AIR

(4) PROPOSED USE: Irrigation

(5) BORE HOLE CONSTRUCTION:

Special Construction Approval NO Depth of Completed Well 385' ft.

Explosives used NO Type _____ Amount _____

| HOLE | | SEAL | | AMOUNT | |
|----------|-----------|----------|---------|--------|--|
| Diameter | From To | Material | From To | Sacks | |
| 8" | 288' 385' | | | | |

How was seal Placed _____

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of Gravel _____

(6) CASING / LINER:

| Dia. | From To | Gage | Material |
|------|---------|------|----------|
| | | | |

Final location of shoe (s) _____

(7) PERFORATIONS / SCREENS:

| METHOD | TYPE: | MATERIAL |
|--------|-------|----------|
| | | |

From To Slot size Number Dia. Tele / pipe size

(8) WELL TESTS:

Minimum testing time is 1 hour

| TESTING METHOD | PUMP |
|----------------|---------------|
| Yield GPM | Drawdown |
| 1100 | 34' |
| | Drill stem at |
| | Time |
| | 2 HOUR |

Temperature of Water 62 F° Depth Artesian Flow Found _____

Was a water analysis done? NO By whom _____

Did any strata contain water not suitable for intended use? No

(9) LOCATION OF WELL by legal description :
 County KLAMATH Latitude _____ Longitude _____
 Township 37 S. Range 14 E.
 Section 2 SW 1/4 NW 1/4
 Tax Lot 1400 Lot _____ Block _____ Subdivision _____
 Street Address of Well (or nearest address)
HWY 140E BLY OR

(10) STATIC WATER LEVEL:

_____ 58 ft. below land surface Date March 26, 2002

Artesian pressure _____ Date _____

(11) WATER BEARING ZONES :

| Depth at which water was first found | | Estimated Flow Rate | SWL |
|--------------------------------------|------|---------------------|-----|
| From | To | | |
| 288' | 385' | 900 GPM | 58' |

(12) WELL LOG:

| | Ground Elevation | | |
|------------------------------------|------------------|-----|-----|
| | FROM | TO | SWL |
| BROKEN GREY & BROWN BASALT | 288 | 327 | 58 |
| BROKEN PURPLE BASALT & RED CINDERS | 327 | 334 | 58 |
| BROKEN GREY & BROWN BASALT | 334 | 385 | 58 |

RECEIVED

RECEIVED APR 2 9 2002

WATER RESOURCES DEPT. SALEM, OREGON

APR 2 3 2002

WATER RESOURCES DEPT. SALEM, OREGON


Date started March 20, 2002 Completed March 26, 2002
 (Unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

[Signature] DATE 4-26-02 WWC # 1452
 (Bonded) Water Well Constructor Certification: I accept responsibility for the construction alteration or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
[Signature] DATE 4-26-02 WWC # 693

300 119600

400

1000



THIS MAP WAS PREPARED FOR
AND FROM THE RECORDS OF THE
COUNTY

SECTION 02 T.37S. R.14E. WM.
KLAMATH COUNTY

37 14 02

SEE MAP 37 14 03

58

113

EEU-06

CAMPBELL RD.

STATE RD. 140 166T

FR

FSM-01

SEE MAP 37 14 01

262.000

SEE MAP 37 14 B

371 12

