

Lake 1179

27S/19E-20dd

State Well No. _____
 State Permit No. _____

(1) OWNER:

Name View Point Ranch
 Address Christmas Valley Ore

(2) TYPE OF WORK (check):

New Well Deepening Reconditioning Abandon
 If abandonment, describe material and procedure in Item 12.

(3) TYPE OF WELL:

Rotary Driven
 Cable Jetted
 Dug Bored

(4) PROPOSED USE (check):

Domestic Industrial Municipal
 Irrigation Test Well Other

(5) CASING INSTALLED:

14" Diam. from 1 ft. to 122 ft. Gage 250
 " Diam. from _____ ft. to _____ ft. Gage _____
 " Diam. from _____ ft. to _____ ft. Gage _____

(6) PERFORATIONS:

Perforated? Yes No.

Type of perforator used _____
 Size of perforations _____ in. by _____ in.
 _____ perforations from _____ ft. to _____ ft.
 _____ perforations from _____ ft. to _____ ft.
 _____ perforations from _____ ft. to _____ ft.

(7) SCREENS:

Well screen installed? Yes No

Manufacturer's Name _____
 Type _____ Model No. _____
 Diam. _____ Slot size _____ Set from _____ ft. to _____ ft.
 Diam. _____ Slot size _____ Set from _____ ft. to _____ ft.

(8) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? Yes No If yes, by whom?
 Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.
 " " " " "
 " " " " "
 Bailer test 30 No draw down gal./min. with _____ ft. drawdown after 2 hrs.
 Artesian flow _____ g.p.m.
 Temperature of water 68 Depth artesian flow encountered no ft.

(9) CONSTRUCTION:

Well seal—Material used Cement
 Well sealed from land surface to 122 ft.
 Diameter of well bore to bottom of seal 17 in.
 Diameter of well bore below seal 14 in.
 Number of sacks of cement used in well seal 2 yds _____ sacks
 Number of sacks of bentonite used in well seal none _____ sacks
 Brand name of bentonite _____
 Number of pounds of bentonite per 100 gallons _____
 of water _____ lbs./100 gals.
 Was a drive shoe used? Yes No Plugs NO Size: location _____ ft.
 Did any strata contain unusable water? Yes No
 Type of water? _____ depth of strata _____
 Method of sealing strata off _____
 Was well gravel packed? Yes No Size of gravel: _____
 Gravel placed from _____ ft. to _____ ft.

(10) LOCATION OF WELL:

County Lake Driller's well number 66
 SE 1/4 SE 1/4 Section 20 T. 27S R. 19E W.M.

Bearing and distance from section or subdivision corner _____

(11) WATER LEVEL: Completed well.

Depth at which water was first found 230 ft.
 Static level 17 ft. below land surface. Date 7/19/72
 Artesian pressure none lbs. per square inch. Date _____

(12) WELL LOG:

Diameter of well below casing 14

Depth drilled 284 ft. Depth of completed well 284 ft.

Formation: Describe color, texture, grain size and structure of materials; and show thickness and nature of each stratum and aquifer penetrated, with at least one entry for each change of formation. Report each change in position of Static Water Level and indicate principal water-bearing strata.

MATERIAL	From	To	SWL
Brown clay	0	31	
Gray clay	31	53	
Green sticky clay	53	96	
Black lava	96	173	
Red lava	173	202	
Black lava	202	260	17
Gray pumice gravel carrying water	260	284	
Well was developed with air by Blaylock Drilling Co. Silver Lake, Ore			

Work started 6/19/72 19 Completed 8/3/72 19
 Date well drilling machine moved off of well 8/5/72 19

Drilling Machine Operator's Certification:

This well was constructed under my direct supervision. Materials used and information reported above are true to my best knowledge and belief.
 [Signed] Denny M. McClane Date 9/3/72 19____
 (Drilling Machine Operator)
 Drilling Machine Operator's License No. 107

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
 Name Denny McClane Well Drilling
 (Person, firm or corporation) (Type or print)
 Address 1607 Austin
 [Signed] Denny M. McClane
 (Water Well Contractor)
 Contractor's License No. 476 Date 9/3/72 19____

LAKE 1179



Oregon Water Resources Department
725 Summer Street NE, Suite A
Salem Oregon 97301
(503) 986-0900
www.wrd.state.or.us

Application for Well ID Number

RECEIVED BY OWRD

Do not complete if the well already has a Well Identification Number.

MAR 28 2016

SALEM, OR

I. OWNER INFORMATION

Current Owner Name (please print): ZX Ranch/View Point Ranch
Mailing Address: PO Box 7
City, State, Zip: Paisley, OR 97636
Mail Well ID Tag to: SAME AS ABOVE In Care Of (C/O)
Name & Address: _____
City, State, Zip: _____

II. WELL LOCATION INFORMATION (Please fill out as completely as possible)

Township: 27 (North South) Range: 19 (East / West) Section: 20 SE 1/4 of the SE 1/4
Tax Lot (usually last 3-5 numbers of Tax Map #): _____ County Lake
GPS Coordinates: _____
Street Address of Well, City: Christmas Valley, Oregon
If the property had a different street address in the past: _____

III. GENERAL WELL INFORMATION (Please fill out as completely as possible, AND attach copy of Well Log, if available)

Use of Well (domestic, irrigation, commercial, industrial, monitoring): Irrigation
Date Well Constructed (or property built): 1972 Total Well Depth: 284 Casing Diameter: _____
Owner at time the well was constructed (if known): View Point Ranch Well Log # (if known): LAKE_1179
Other Information: _____

SUBMITTED BY (please print): Daphne Story
PHONE: 541-943-3105 EMAIL &/or FAX: daphne.story@simplot.com

Send application to: Oregon Water Resources Department 725 Summer St NE, Suite A, Salem, Oregon 97301; or fax to (503) 986-0902.
Applications are processed in the order they are received, and Well ID Numbers are mailed within 4-5 business days.

For Official Use Only by the Oregon Water Resources Department:

Received Date:

3-28-16

Well Log Number:

LAKE 1179

Well Identification #:

L-122404