

RECEIVED
APR 1 1959

LAKE 1182

Lake 1182

27 APR 1959 G(1)

File Original and First Copy with the STATE ENGINEER, SALEM, OREGON

STATE ENGINEER
SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

State Well No. ~~1182~~

State Permit No. G 1232

G 2085

(1) OWNER:

Name View Point Ranches Inc. *George & Joan Brown*
Address Silver Lake Oregon

(2) LOCATION OF WELL:

County Lake Owner's number, if any—
1/4 1/4 Section T. R. W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

New Well Deepening Reconditioning Abandon
Abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic Industrial Municipal
Irrigation Test Well Other

(5) TYPE OF WELL:

Rotary Driven
Cable Jetted
Dug Bored

(6) CASING INSTALLED:

Threaded Welded
16" Diam. from 00 ft. to 10 ft. Gage
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS:

Perforated? Yes No

Type of perforator used

SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:

Well screen installed Yes No

Manufacturer's Name
Model No.
Slot size Set from ft. to ft.
Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Was well gravel packed? Yes No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? Yes No To what depth? ft.
Material used in seal—
Did any strata contain unusable water? Yes No
Type of water? Soft Depth of strata
Method of sealing strata off

(10) WATER LEVELS:

Static level ft. below land surface Date
Artesian pressure lbs. per square inch Date

Log Accepted by:

[Signed] *Da Shelbo* Date 3-30, 1959
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? Yes No If yes, by whom? Western Pump

Yield: 2400 gal./min. with 13 ft. drawdown after 8 hrs.

" " " "

Bailer test gal./min. with ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? Yes No

(12) WELL LOG:

Diameter of well 15 inches.

Depth drilled 315 ft. Depth of completed well 314 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
* 0-10 ft.		
Sandy Clay	0	37
Course pumas sand	57	63
Sandy Clay	63	82
Gray Rock	82	97
Soft Lava Rock	97	104
Dark Gray clay	104	124
Gray Sindens	124	130
Gray Clay	130	178
Gray Rock	178	224
Gray and Red sinders	224	234
Basalt	234	284
Sindens	284	314

Work started Dec 1 1958 Completed Jan 10 1959

(13) PUMP:

Manufacturer's Name
Type: H.P.

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Frank Skillings
(Person, firm, or corporation) (Type or print)

Address Rt. 1 Box 243 Corvallis

Driller's well number 11

[Signed] *Frank Skillings*
(Well Driller)

License No. 214 Date Feb 5, 1959

LAKE 1182



Oregon Water Resources Department
725 Summer Street NE, Suite A
Salem Oregon 97301
(503) 986-0900
www.wrd.state.or.us

Application for Well ID Number

RECEIVED BY OWRD

MAR 28 2016

SALEM, OR

Do not complete if the well already has a Well Identification Number.

I. OWNER INFORMATION

Current Owner Name (please print): ZX Ranch/View Point Ranch

Mailing Address: PO Box 7

City, State, Zip: Paisley, OR 97636

Mail Well ID Tag to: SAME AS ABOVE In Care Of (C/O)

Name & Address: _____

City, State, Zip: _____

II. WELL LOCATION INFORMATION (Please fill out as completely as possible)

Township: 27 (North ~~South~~) Range: 19 (~~East~~ West) Section: 19 _____ 1/4 of the _____ 1/4

Tax Lot (usually last 3-5 numbers of Tax Map #): 2800 County Lake

GPS Coordinates: _____

Street Address of Well, City: Christmas Valley, Oregon

If the property had a different street address in the past: _____

III. GENERAL WELL INFORMATION (Please fill out as completely as possible, AND attach copy of Well Log, if available)

Use of Well (domestic, irrigation, commercial, industrial, monitoring): Irrigation

Date Well Constructed (or property built): 1959 Total Well Depth: 314 Casing Diameter: _____

Owner at time the well was constructed (if known): View Point Ranch Well Log # (if known): LAKE_1182

Other Information: All of above T.R.S. is Tax lot 2800

SUBMITTED BY (please print): Daphne Story

PHONE: 541-943-3105

EMAIL &/or FAX: daphne.story@simplot.com

Send application to: Oregon Water Resources Department 725 Summer St NE, Suite A, Salem, Oregon 97301; or fax to (503) 986-0902. Applications are processed in the order they are received, and Well ID Numbers are mailed within 4-5 business days.

For Official Use Only by the Oregon Water Resources Department:

Received Date:

3-28-16

Well Log Number:

LAKE 1182

Well Identification #:

L-122402