STATE OF OREGON

WATER WELL REPORT

(as required by ORS 537.765)

Lake 3100

RECEIVED

MAY 17 1989

WATER RESOURCES DEPT. SALEM, OREGON

268/18E/25cd

(START CARD) # 1022

(1) OWNER:

Well Number: WA

Name Richard C. Smith

Address 4453 18th Ave. N.E.

City Salem State Ore Zip 97303

(2) TYPE OF WORK:

☐ New Well ☑ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☑ Cable

☐ Other

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation

☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes ☐ No ☐ Depth of Completed Well ____ ft.

Explosives used Yes ☐ No ☐ Type ____ Amount ____

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
12	200	285				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☑ Other Seal Not Disturbed

Backfill placed from ____ ft. to ____ ft. Material ____

Gravel placed from ____ ft. to ____ ft. Size of gravel ____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
None Installed					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) ____

(7) PERFORATIONS/SCREENS:

☐ Perforations Method ____

☐ Screens Type ____ Material ____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
None Installed						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
20	0		1 hr.

Temperature of water 52° Depth Artesian Flow Found ____

Was a water analysis done? NO ☐ Yes By whom ____

Did any strata contain water not suitable for intended use? ☑ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other ____

Depth of strata: ____

(9) LOCATION OF WELL by legal description:

County Lake Latitude ____ ' ____ " Longitude ____ ' ____ "

Township 26 S ~~Nor~~ S, Range 18 E E or ~~W, WM.~~

Section 25 SE ¼ SW ¼

Tax Lot ____ Lot ____ Block ____ Subdivision ____

Street Address of Well (or nearest address) Christmas Valley, Ore. 97641

(10) STATIC WATER LEVEL:

31 ft. below land surface. Date 2-20-89

Artesian pressure ____ lb. per square inch. Date ____

(11) WATER BEARING ZONES:

Depth at which water was first found ____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:

Ground elevation ____

Material	From	To	SWL
Clay gray	200	285	31'

Date started 8-5-89 Completed 3-9-89

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number 657

Signed Claude Blackburn Date 5-15-89

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 657

Signed Claude Blackburn Date 5-15-89