STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

LAKE 4189

RECEIVED
JUN 26 1992
WATER RESOURCES DEPT
SALEM, OREGON

27S/17E/7
(START CARD) # 27249

(1) OWNER: Well Number
Name GOLDEN RULE FARMS
Address Christmas Valley
City State Or Zip 97641

(2) TYPE OF WORK:
☐ New Well ☐ Deepen ☑ Recondition ☐ Abandon

(3) DRILL METHOD:
☑ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☐ No Depth of Completed Well 800 ft.
Explosives used ☐ Yes ☐ No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
	525	800				
Cleaned out hole						

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
	Casing Added				☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	NA				☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☑ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
[redacted]	[redacted]		1 hr.
1200		800	

Temperature of Water 56 Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County LAKE Latitude Longitude
Township 27S N or S. Range 17E E or W. WM.
Section 7 ¼ ¼
Tax Lot Lot Block Subdivision
Street Address of Well (or nearest address) Christmas Valley RD area

(10) STATIC WATER LEVEL:
43 ft. below land surface. Date 5-26-92
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:
Ground elevation 4130

Material	From	To	SWL
Cleaned out hole			

Date started 5-16-92 Completed 5-24-92

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief. WWC Number 367
Signed Melvin Leach Date 5-26-92

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91