

LAKE 52853

WELL I.D. # L _____

(1) LAND OWNER 2A Ranch Inc. Well Number _____
 Name 2A Ranch Inc.
 Address _____
 City _____ State OR Zip _____

(2) TYPE OF WORK
 New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:
 Rotary Air Rotary Mud Cable Auger
 Other _____

(4) PROPOSED USE:
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other _____

(5) BORE HOLE CONSTRUCTION:
 Special Construction approval Yes No Depth of Completed Well 280 ft.
 Explosives used Yes No Type _____ Amount APP

HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks or pounds

How was seal placed: Method A B C D E
 Other _____
 Backfill placed from _____ ft. to _____ ft. Material _____
 Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 12"	0	260		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Liner:				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used Inside Outside None
 Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour

Yield gal/min	Drawdown	Drill stem at	Time 1 hr.

Temperature of water _____ Depth Artesian Flow Found _____
 Was a water analysis done? Yes By whom _____
 Did any strata contain water not suitable for intended use? Too little
 Salty Muddy Odor Colored Other _____
 Depth of strata: _____

(9) LOCATION OF WELL by legal description:
 County Lake Latitude _____ Longitude _____
 Township 31 N or S Range 16 E or W. WM.
 Section 10 SE 1/4 SW 1/4
 Tax Lot _____ Lot _____ Block _____ Subdivision _____
 Street Address of Well (or nearest address) _____

(10) STATIC WATER LEVEL: APP
~22 ft. below land surface. 6-11134 Date _____
 Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES:
 Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:
 Ground Elevation _____

Material	From	To	SWL
This is well #2 on applications 6-11134 and 6-15162. Location information appears to be consistent throughout these two files. The earliest construction information found comes from application 6-11134, received by OWBD 10-10-1983 and stoned by Verle Emery. Subsequent construction information comes from Wayne Lechmann, the ranch foreman, from a final proof survey by P.M. Sullerfeld on 8-26-1993 and on application 6-15162. The well was drilled by Charles Stadeli sometime prior to October 1984 and is likely between 256 and 285 feet deep. Depth to water is estimated to be between 20 and 30 feet.			

Date started _____ Completed _____

SOURCE OF DATA/INFO Groundwater Application Files 6-11134 and 6-15162.

COMPILED BY: Halley Barnett
Groundwater Section

DATE: 8/14/2018

APP 6-11134