

STATE OF OREGON WATER SUPPLY WELL REPORT

LAKE 55198

WELL I.D. LABEL# L

152534

START CARD #

1079336

ORIGINAL LOG #

LAKE

4307

2/8/2026

(as required by ORS 537.545 & 537.765 and OAR 690-205-0210)

(1) LAND OWNER

Owner Well I.D.

First Name DUST Last Name GRASSMAN
Company
Address 57018 MILLCAN RD
City CHRISTMAS VALLEY State OR Zip 97641

(2) TYPE OF WORK

New Well Deepening Conversion
Alteration (complete 2a & 10) Abandonment (complete 5a)

(2a) PRE-ALTERATION

Casing: Dia + From To Gauge Std Plstc Wld Thrd
Material From To Amt sacks/lbs
Seal:

(3) DRILL METHOD

Rotary Air Rotary Mud Cable Auger Cable Mud
Reverse Rotary Other

(4) PROPOSED USE

Domestic Irrigation Community
Industrial/ Commercial Livestock Dewatering
Thermal Injection Other

(5) BORE HOLE CONSTRUCTION

Special Standard (Attach copy)

Depth of Completed Well ft.

Table with columns: Dia, From, To, Material, SEAL, From, To, Amt, sacks/lbs. Includes rows for Calculated and Actual values.

Seal placement method: A B C D E Other: poured

Backfill placed from ft. to ft. Material

Filter pack from ft. to ft. Material Size

Explosives used: Type Amount

Seal Placement Begin Date 1/14/2026 Begin Time 09 30

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Actual Amount

(6) CASING/LINER

Table with columns: C/L, Dia, +, From, To, Gauge, Mat. Type, Wld, Thrd, Shoe, Location

Temp casing Yes Dia From+ To

(7) PERFORATIONS/SCREENS

Perforations Method

Screens Type Material

Table with columns: Perf/ Screen, Casing/ Liner, Dia, From, To, Scrm/slot width, Slot length, # of slots, Tele/ Pipe size

(8) WELL TESTS: Minimum testing time is 1 hour

Table with columns: Type of Test, Yield (gal/min), Drawdown, Drill Stem/ Pump Depth, Duration (hr)

Temperature 52 °F Lab analysis Yes By

Water quality concerns? Yes (describe below) TDS amount 299 ppm

Table with columns: From, To, Description, Amount, Units

(9) LOCATION OF WELL (legal description)

County LAKE Twp 27.00 S N/S Range 17.00 E E/W WM
Sec 1 NW 1/4 of the SE 1/4 Tax Lot 1200
Tax Map Number Lot
Lat 43.25571814 DMS or DD
Long -120.64609640 DMS or DD

Street address of well Nearest address

57018 MILL CAN RD CHRISTMAS VALLEY OR 97641

(10) STATIC WATER LEVEL

Table with columns: Date, SWL(psi), SWL(ft), Existing Well / Pre-Alteration, Completed Well

Flowing Artesian? Dry Hole?

WATER BEARING ZONES

Depth water was first found

SWL Date From To Est Flow SWL(psi) + SWL(ft)

Table for water bearing zones with columns: SWL Date, From, To, Est Flow, SWL(psi), + SWL(ft)

(11) WELL LOG

Ground Elevation 4318.80 FT

Table for well log with columns: Material, From, To

Construction

Begin Date 11/25/2025 Begin Time 08 20 End Date 1/14/2026

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.

License Number Date

Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above.

License Number 1654 Date 2/8/2026

Signed TOM SEARCH (E-filed)

Drilling Company: search drilling h20 Limited Tom Search

