RECEIVED

SEP 1 2 1996

WATER RESOURCES DEPT.
SALEM, OREGON

#L06819

STATE OF OREGON
WATER SUPPLY WELL REPORT lane
(as required by ORS 537.765) 51309
Instructions for completing this report are on the last page of this form.

(START CARD) # 82358

(1) OWNER: Well Number

Name Mary Lou Hanna
Address 8251 N 3rd Place
City Springfield State OR Zip 97477

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [X] No Depth of Completed Well 90 ft.
Explosives used [ ] Yes [X] No Type Amount

| HOLE Diameter | From | To | SEAL Material | From | To | Sacks or pounds |
|---|---|---|---|---|---|---|
| 10" | 0 | 40 | Bentonite | 0 | 40 | 21 |
| | | | | | | |
| 6 | 40 | 90 | | | | |

How was seal placed: Method [ ] A [ ] B [X] C [ ] D [ ] E
[ ] Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

| | Diameter | From | To | Gauge | Steel | Plastic | Welded | Threaded |
|---|---|---|---|---|---|---|---|---|
| Casing: | 6" | +1 | 70 | 250 | ✓ | | ✓ | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Liner: | 4" | 0 | 80 | .21 | | ✓ | ✓ | |
| | | | | | | | | |

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
[ ] Perforations Method
[X] Screens Type Westco Material

| From | To | Slot size | Number | Diameter | Tele/pipe size | Casing | Liner |
|---|---|---|---|---|---|---|---|
| 80 | 90 | .008 | | | 4" | | ✓ |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

| Yield gal/min | Drawdown | Drill stem at | Time |
|---|---|---|---|
| 15 | | 90 | 1 hr. |
| | | | |
| | | | |

Temperature of water 55 Depth Artesian Flow Found
Was a water analysis done? [ ] Yes By whom
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County lane Latitude 4356.91 N Longitude 124°06.05 W
Township 19 N or (S) Range 12 E or (W) WM.
Section 02 1/4 1/4
Tax Lot 2602 Lot Block Subdivision
Street Address of Well (or nearest address)
85168 Pike st Florence OR 97439

(10) STATIC WATER LEVEL:
25 ft. below land surface. Date Sept 4
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 80

| From | To | Estimated Flow Rate | SWL |
|---|---|---|---|
| 80 | 90 | 15 gpm | 25 |
| | | | |
| | | | |
| | | | |
| | | | |

(12) WELL LOG:
Ground Elevation

| Material | From | To | SWL |
|---|---|---|---|
| Brown sand | 0 | 50 | |
| Yellow | 50 | 80 | |
| Brown sand | 80 | 90 | 25 |

Date started Sept 4 Completed Sep 4

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 1553
Signed Jeffrey Henderickson Date 9-4-96

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER