LANE 56935

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

WELL I.D. # L 22598
START CARD # 112706

(1) OWNER: Well Number L22598
Name SDH Enterprises ~~SDH~~ LLC
Address 23421 Hwy 36
City Cheshire State OR Zip 97419

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:
[ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [X] No Depth of Completed Well 130 ft.
Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10	0	30	Bentonite	0	30	17
6	30	130				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other Poured Dry and tamped
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	0 ft	38	.25	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) 38'

(7) PERFORATIONS/SCREENS:
[ ] Perforations Method
[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
20 gpm	10		1 hr.

Temperature of water 53° Depth Artesian Flow Found
Was a water analysis done? [ ] Yes By whom
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Lane Latitude Longitude
Township 16 N or [X] Range 05 E or [X] WM.
Section 21 SE 1/4 SW 1/4
Tax Lot 2600 Lot 1 Block Subdivision
Street Address of Well (or nearest address) 92021 Territorial Rd
Junction city

(10) STATIC WATER LEVEL:
50 ft. below land surface. Date 4/23/99
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 85'

From	To	Estimated Flow Rate	SWL
85	120	5 gpm	50
120	130	20 gpm	50

(12) WELL LOG:
Ground Elevation

Material	From	To	SWL
Top soil	0	10	
Orange Clay	10	22	
Gray Sand stone	22	120	50
Blue Sand stone	120	130	50

RECEIVED
MAY 11 1999
WATER RESOURCES DEPT.
SALEM, OREGON

Date started 4/20/99 Completed 4/23/99

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number 1696
Signed Derek Madsen Date 4/28/99

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 1635
Signed Jerry C Madsen Date 4/28/99

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER