LANE 58810

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

WELL I.D. # L L-40777
START CARD # 131229

(1) OWNER: Well Number L40777
Name LEO MURPHY
Address SOUTH CANARY ROAD
City WESTLAKE State OR. Zip 97493

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [X] No Depth of Completed Well 142 ft.
Explosives used [ ] Yes [X] No Type — Amount —

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	39	Bentonite	0	39	15
6"	39	142				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other POURED & TAMPED
Backfill placed from — ft. to — ft. Material —
Gravel placed from — ft. to — ft. Size of gravel —

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	39	250	[X]	[ ]	[X]	[ ]
Liner:	4"	-2	142	160	[ ]	[X]	[ ]	[ ]

Final location of shoe(s) NONE

(7) PERFORATIONS/SCREENS:
[X] Perforations Method SKILSAW
[ ] Screens Type SLOT Material PVC

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
-22	140	6"	120	1/8"	4"	[ ]	[X]

(8) WELL TESTS: Minimum testing time is 1 hour
[X] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
10	—	—	1 hr.

Temperature of water 53° Depth Artesian Flow Found —
Was a water analysis done? [ ] Yes By whom NO
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other NO
Depth of strata: NONE

(9) LOCATION OF WELL by legal description:
County LANE Latitude — Longitude —
Township 20 N or (S) Range 11 E or (W) WM.
Section 06 NE 1/4 NE 1/4
Tax Lot 900 Lot — Block — Subdivision —
Street Address of Well (or nearest address) FIRST DRIVEWAY ON RIGHT - SOUTH CANARY ROAD

(10) STATIC WATER LEVEL:
25' ft. below land surface. Date 08/18/00
Artesian pressure — lb. per square inch. Date —

(11) WATER BEARING ZONES:
Depth at which water was first found 130'

From	To	Estimated Flow Rate	SWL
130'	133'	10 GPM	25

(12) WELL LOG:
Ground Elevation APPROX 200'

Material	From	To	SWL
TOPSOIL	0	2	
CLAY SANDY YELLOW	2	14	
CLAY GREY	14	18	
SANDSTONE BR. BROKEN	18	33	
SANDSTONE GREY	33	130	
SANDSTONE GREY FRAC	130	133	
SANDSTONE GREY	133	140	

RECEIVED
OCT 11 2000
WATER RESOURCES DEPT.
SALEM, OREGON

Date started 08/18/00 Completed 08/18/00

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 613
Signed KIRT E. LEE Date 10/05/00

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER

Water Fin log
Died 08/24/00