LANE 73103

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

DRAFT

WELL I.D. # L not tagged/ Lane 14945

START CARD # 208025

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number _____
Name Rick Wilhite
Address 49589 McKenzie Hwy
City Vida State OR Zip 97488

(2) TYPE OF WORK ☐ New Well
☐ Deepening ☑ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☑ Cable ☐ Auger ☐ Cable Mud
☐ Other _____

(4) PROPOSED USE
☑ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION Special Construction: ☐ Yes ☑ No
Depth of Completed Well 80 ft.
Explosives used: ☐ Yes ☑ No Type _____ Amount _____

BORE HOLE Diameter	From	To	SEAL Material	From	To	Sacks or Pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	4"	0'	80'	160psi	☐	☑	☑	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☑ None
Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS
☑ Perforations Method drill
☐ Screens Type 3/8" Material _____

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
34'	80'	3/8	46	4"	pipesize	☐	☑
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time

Temperature of water _____ Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL (legal description)
County Lane
Tax Lot 401 Lot _____
Township 17 S Range 3 E WM
Section 2 SE 1/4 NW 1/4

Lat ___°___'___" or _____.____ (degrees or decimal)
Long ___°___'___" or _____.____ (degrees or decimal)

Street Address of Well (or nearest address) 49589 McKenzie Hwy
Vida, OR 97488

(10) STATIC WATER LEVEL
14 ft. below land surface. Date 2/14/11
_____ ft. below land surface. Date _____
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES
Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG Ground Elevation _____

Material	From	To	SWL
packer set from 32'-34'			

RECEIVED BY OWRD
APR 28 2014
SALEM

Date Started 12-14-11 Completed 12-14-11

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number 1886 Date _____
Signed _____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 636 Date _____
Signed _____