

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM, OREGON
within 30 days from the date
of well completion.

NOV 3

REPORT 65

LANE
7364
C-5150

State Well No. 10/343-1 ac

State Permit No. _____

Name Norman Clark
Address 826 P. Street
 Eugene, Oregon

County Gene Driller's well number _____
 _____ ¼ _____ ¼ Section 7 T. 16S R. 3W W.M.
 Bearing and distance from section or subdivision corner

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

Domestic ☒ Industrial ☐ Municipal ☐ Rotary ☐ Driven ☐
Irrigation ☐ Test Well ☐ Other ☐ Cable ☒ Jetted ☐
Dug ☐ Bored ☐

Rotary	☐	Driven	☐
Cable	☒	Jettied	☐
Dug	☐	Bored	☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒
 6" Diam. from 0 ft. to 37 ft. Gage .25
 " Diam. from " ft. to " ft. Gage "
 " Diam. from " ft. to " ft. Gage "

Perforated? ☐ Yes ☐ No

Type of perforator used	<i>torch</i>			
Size of perforations	<i>1/4</i>	in. by	<i>8</i>	in.
..... perforations from		ft. to		ft.
<i>24</i> perforations from	<i>32</i>	ft. to	<i>37</i>	ft.
..... perforations from		ft. to		ft.
..... perforations from		ft. to		ft.
..... perforations from		ft. to		ft.

Well screen installed? ☐ Yes ☐ No

Manufacturer's Name Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

Well seal—Material used in seal Bentonite

Depth of seal 18 ft. Was a packer used? No

Diameter of well bore to bottom of seal 9 in.

Were any loose strata cemented off? ☐ Yes ☒ No Depth _____

Was a drive shoe used? ☒ Yes ☐ No _____

Was well gravel packed? ☐ Yes ☒ No Size of gravel: _____

Gravel placed from _____ ft. to _____ ft.

Did any strata contain unusable water? ☐ Yes ☒ No

Type of water? _____ depth of strata _____

Method of sealing strata off _____

Static level 17 ft. below land surface Date 18-OCT-65
Artesian pressure _____ lbs. per square inch Date _____

Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield:	gal./min. with	ft. drawdown after	hrs
"	"	"	"
"	"	"	"

Bailer test 35 gal./min. with 14 ft. drawdown after 2 hrs

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☐ No

Diameter of well below casing 6

Depth drilled 37 ft. Depth of completed well 37 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation

[illegible]

Work started 12 OCT. 19 65 Completed 17 OCT. 19 65

Date well drilling machine moved off of well 18 OCT. 1965-

Manufacturer's Name

Type: H.P.

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME **CHRISTENSEN DRILLING & IRRIGATION**
(Person, firm or corporation) **244 4205** (Type or print)

Address 3550 West 16th Ph. 544-4205
Eugene, Oregon 97402

Drilling Machine Operator's License No. 406

[Signed] Mark Christensen
(Water Well Contractor)

Contractor's License No. 97 Date 19 OCT. 19 65