OBSERVATION WELL

LINC

RECEIVED SEP 19 1962 STATE ENGINEER

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

LINC 1138

State Well No. 11/10W-20L(1)

State Permit No.

(1) OWNER: JOSEPH W. BROWN OREGON
Name Mrs. Anna Davenport
Address Rt 1 Box 595
Toledo Oregon

(2) LOCATION OF WELL:
County Lincoln Driller's well number
¼ ¼ Section 20 T. 11-S R. 10-W W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):
New Well ☑ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☑ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☐ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☑
6" Diam. from 0 ft. to 50 ft. Gage .250
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☑ No
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☐ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal Shield Leaf Bentonite
Depth of seal 26 ft. Was a packer used? No
Diameter of well bore to bottom of seal 10 in.
Were any loose strata cemented off? ☐ Yes ☑ No Depth
Was a drive shoe used? ☐ Yes ☑ No
Was well gravel packed? ☐ Yes ☑ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☑ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS: 53.94 ft 9-17-64 USGS
45.14 ft 2-26-65 RD
Static level 50 ft. below land surface. Date Sept 12-62
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☑ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test .75 gal./min. with 8 ft. drawdown after 1 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG: Diameter of well below casing 6
Depth drilled 87 ft. Depth of completed well 87 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Soil	0	4
Clay (yellow soft	4	30
Clay stone Blue	30	70
Clay stone (Broken, water)	70	87
Bottom		

Work started Sept 12 1962 Completed 19
Date well drilling machine moved off of well 19

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
NAME G H Pruitt Well Drilling (Person, firm or corporation) (Type or print)
Address Rt 1 Box 53 Corvallis
Drilling Machine Operator's License No.
[Signed] Delbert A. Pruitt (Water Well Contractor)
Contractor's License No. 23 Date , 19

(USE ADDITIONAL SHEETS IF NECESSARY)