

WATER WELL REPORT

STATE OF OREGON

State Well No.

State Permit No.

(1) OWNER:

Name B.T. Billings
Address Rt 1 Box 16
Sele, Ore.

(2) LOCATION OF WELL:

County Linn Owner's number, if any—
1/4 1/4 Section 33 T. 9 R. 1 W.M.
Bearing and distance from section or subdivision corner
Linn Co Oregon, South east corner
Section 33

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:

8 5/8" Diam. from 140 ft. to 16 ft. Threaded ☐ Welded ☒
Gage 277
" Diam. from _____ ft. to _____ ft. Gage _____
" Diam. from _____ ft. to _____ ft. Gage _____

(7) PERFORATIONS:

Perforated? ☐ Yes ☒ No

Type of perforator used _____

SIZE of perforations	in.	by	in.
perforations from _____	ft.	to _____	ft.
perforations from _____	ft.	to _____	ft.
perforations from _____	ft.	to _____	ft.
perforations from _____	ft.	to _____	ft.
perforations from _____	ft.	to _____	ft.

(8) SCREENS:

Well screen installed ☐ Yes ☒ No

Manufacturer's Name _____
Type _____ Model No. _____
Diam. Slot size _____ Set from _____ ft. to _____ ft.
Diam. Slot size _____ Set from _____ ft. to _____ ft.

(9) CONSTRUCTION:

Was well gravel packed? ☐ Yes ☒ No Size of gravel: _____
Gravel placed from _____ ft. to _____ ft.
Was a surface seal provided? ☐ Yes ☐ No To what depth? _____ ft.
Material used in seal—
Did any strata contain unusable water? ☐ Yes ☐ No
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(10) WATER LEVELS:

Static level 2 above ft. below land surface Date 5/31/60
Artesian pressure _____ lbs. per square inch Date _____

Log Accepted by _____

[Signed] B.T. Billings Date 6-2, 1960
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom? _____

Yield:	gal./min. with	ft. drawdown after	hrs.
"	"	"	"
"	"	"	"

Bailer test 33 1/2 gal./min. with 85 ft. drawdown after 1 1/2 hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG:

Diameter of well _____ inches.

Depth drilled 105 ft. Depth of completed well 105 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Top soil & broken rock	0	3
Basalt (fresh)	3	21
Volcanic ash	21	23
Basalt (fresh)	23	77
Old land surface (soft)	77	81
Basalt (fresh)	81	84
Old land surface (carboniferous wood present)	84	90
Basalt (fresh)	90	105

Work started 5/23 1960 Completed 5/31/60 19

(13) PUMP:

Manufacturer's Name Fairbanks-Morse
Type: Submersible 13 stage H.P. 1

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Robinson Drilling & Supply
(Person, firm, or corporation) (Type or print)

Address 140 Pine St NE Salem, Ore

Driller's well number 9/1W-41

[Signed] Harry A. Robinson
(Well Driller)

License No. 22 Date 6/1/60, 19