

NOTICE TO WATER WELL CONTRACTOR

The original and first copy
of this report are to be
filed with the

STATE ENGINEER, SALEM 10, OREGON
within 30 days from the date
of well completion.

WATER WELL REPORT 7 1962

STATE OF OREGON
(Please type or print)
SALEM, OREGON

State Well No. 10/1w-18
State Permit No. _____

(1) OWNER:

Name City of Scio

Address Scio, Oregon.

(2) LOCATION OF WELL:

County Linn Driller's well number _____

$\frac{1}{4}$ $\frac{1}{4}$ Section 18 T. 10 S R. 1 W W.M.

Bearing and distance from section or subdivision corner _____

TYPE OF WORK (check):

New Well ☐ Deepening ☐ Reconditioning ☒ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☐ Industrial ☐ Municipal ☒ Rotary ☐ Driven ☐
Irrigation ☐ Test Well ☐ Other ☐ Cable ☐ Jetted ☐
Dug ☐ Bored ☐

(5) TYPE OF WELL:

(6) CASING INSTALLED:

Threaded ☐ Welded ☐

" Diam. from _____ ft. to _____ ft. Gage _____

" Diam. from _____ ft. to _____ ft. Gage _____

" Diam. from _____ ft. to _____ ft. Gage _____

(7) PERFORATIONS:

Perforated? ☐ Yes ☐ No

Type of perforator used _____

Size of perforations _____ in. by _____ in.

_____ perforations from 159 ft. to 210 ft.

_____ perforations from _____ ft. to _____ ft.

_____ perforations from _____ ft. to _____ ft.

_____ perforations from _____ ft. to _____ ft.

_____ perforations from _____ ft. to _____ ft.

(8) SCREENS:

Well screen installed ☐ Yes ☐ No

Manufacturer's Name _____

Type _____ Model No. _____

Diam. _____ Slot size _____ Set from _____ ft. to _____ ft.

Diam. _____ Slot size _____ Set from _____ ft. to _____ ft.

(9) CONSTRUCTION:

Well seal—Material used in seal _____

Depth of seal _____ ft. Was a packer used? _____

Diameter of well bore to bottom of seal _____ in.

Were any loose strata cemented off? ☐ Yes ☐ No Depth _____

Was a drive shoe used? ☐ Yes ☐ No

Was well gravel packed? ☐ Yes ☐ No Size of gravel: _____

Gravel placed from _____ ft. to _____ ft.

Did any strata contain unusable water? ☐ Yes ☐ No

Type of water? _____ Depth of strata _____

Method of sealing strata off _____

(10) WATER LEVELS:

Static level _____ ft. below land surface Date _____

Artesian pressure _____ lbs. per square inch Date _____

RECEIVED

(11) WELL TESTS:

Drawdown is amount water level is
lowered below static level

Was a pump test made? ☐ Yes ☐ No If yes, by whom?

Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.

" " " "

" " " "

Bailer test _____ gal./min. with _____ ft. drawdown after _____ hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG:

Diameter of well below casing 8"

Depth drilled _____ ft. Depth of completed well 215 ft.

Formation: Describe by color, character, size of material and structure, and
show thickness of aquifers and the kind and nature of the material in each
stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Sand & gravel	<u>203</u>	<u>210</u>
Blue Clay	<u>210</u>	<u>215</u>

Cleaned 10" well from 188 feet to
203 feet

Drilled to 210 ft. with 10" Bit

Put 51 ft. of 8" liner with shoe

on top and bottom. Drilled 5' below

liner to 215 feet.

Bottom of liner set at 210 ft.,

top at 159 feet.

Work started Aug. 10 19 62 Completed Aug. 14 19 62

Date well drilling machine moved off of well Aug. 15 19 62

(13) PUMP:

Manufacturer's Name _____

Type: _____ H.P. _____

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is
true to the best of my knowledge and belief.

NAME Barron & Strayer
(Person, firm or corporation) (Type or print)

Address Rt. 1, box 254, Beaverton, Ore.

Drilling Machine Operator's License No. _____

[Signed] A. J. Barron
(Water Well Contractor)

Contractor's License No. 35 Date Aug. 18, 19 62