LINN
4645

FEB 24 1959
STATE ENGINEER
SALEM, OREGON

File Original and First Copy with the STATE ENGINEER, SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

State Well No. 10/3W-9E(2)

State Permit No. G 1393

(1) OWNER:

Name: Cecil Cox

Address: Rt. # 2, Albany, Oregon

(2) LOCATION OF WELL:

County: ~~Benton~~ LINN Owner's number, if any—

SW ¼ NW ¼ Section 9 T. 10S. R. 3W. W.M.

Bearing and distance from section or subdivision corner: S. 28° 45' E. 34.5 CHAINS FROM THE NW CORNER OF S.9, T.10S., R.3W.

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐

If abandonment, describe material and procedure in Item 11.

PROPOSED USE (check):

Domestic ☐ Industrial ☐ Municipal ☐

Irrigation ☒ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐

Cable ☒ Jetted ☐

Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒

8" Diam. from 0 ft. to 31 ft. Gage 17#

" Diam. from ft. to ft. Gage

" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☒ Yes ☐ No

Type of perforator used: Acetylene Torch

SIZE of perforations ¼ in. by 12 in.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☒ No

Manufacturer's Name

Type Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Was well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Was a surface seal provided? ☐ Yes ☒ No To what depth? ft.

Material used in seal—

Did any strata contain unusable water? ☐ Yes ☒ No

Type of water? Depth of strata

Method of sealing strata off

(10) WATER LEVELS:

Static level 16½ ft. below land surface Date 8-23-58

Artesian pressure lbs. per square inch Date

Log Accepted by:

[Signed] Cecil E. Cox (Owner) Date 2/18, 1959

(11) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.

" " " "

" " " "

Bailer test 90 gal./min. with NO ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well 8 inches.

Depth drilled 31 ft. Depth of completed well 31 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Top Soil	NONE	
River Boulders	0	22
Gravel	22	31

Work started 8-20 1958. Completed 8-23 1958

(13) PUMP:

Manufacturer's Name: FAIRBANKS MORSE

Type: 2½" CENTRIFUGAL H.P. 10

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME: Merle E. Warren, Well Drilling (Person, firm, or corporation) (Type or print)

Address: 1315 W. 15th Ave., Albany, Oregon

Driller's well number

[Signed] Merle Warren (Well Driller)

License No. 182 Date 2-18, 1959

(USE ADDITIONAL SHEETS IF NECESSARY)