Linn 5117

RECEIVED
SEP - 3 1997
WATER RESOURCES DEPT.
SALEM, OREGON

STATE OF OREGON WELL I.D.# L10139
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)
Instructions for completing this report are on the last page of this form.

(START CARD) # 99398

(1) OWNER: Well Number 3142
Name Mark Elder
Address 605 Erin Crest DW
City Albany State OR Zip 9732

(2) TYPE OF WORK
[X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD:
[X] Rotary Air [] Rotary Mud [] Cable [] Auger
[] Other

(4) PROPOSED USE:
[X] Domestic [] Community [] Industrial [] Irrigation
[] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [] Yes [X] No Depth of Completed Well 80 ft.
Explosives used [] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10	0	25	Bentonite	0	25	15 sacks
6	0	80	Bore			

How was seal placed: Method [] A [] B [X] C [] D [] E
[] Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	1	79	250	[X]	[]	[X]	[]
					[]	[]	[]	[]
					[]	[]	[]	[]
					[]	[]	[]	[]
Liner:	None				[]	[]	[]	[]
					[]	[]	[]	[]

Final location of shoe(s) None

(7) PERFORATIONS/SCREENS:
[X] Perforations Method Holte
[] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
70	75	1/4x1	400		6	[X]	[]
						[]	[]
						[]	[]
						[]	[]
						[]	[]

(8) WELL TESTS: Minimum testing time is 1 hour
[] Pump [] Bailer [X] Air [] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
100 gpm		70	1 hr.

Temperature of water 56 Depth Artesian Flow Found
Was a water analysis done? [] Yes By whom
Did any strata contain water not suitable for intended use? [] Too little
[] Salty [] Muddy [] Odor [] Colored [] Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Linn Latitude Longitude
Township 13 N or (S) Range 3 E or (W) WM.
Section 21 SW 1/4 SW 1/4
Tax Lot 400 Lot Block Subdivision
Street Address of Well (or nearest address) Ogle Rd.
Shedd, OR

(10) STATIC WATER LEVEL:
13 ft. below land surface. Date 8-26-97
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 40

From	To	Estimated Flow Rate	SWL
40	75	100 gpm	13

(12) WELL LOG:
Ground Elevation

Material	From	To	SWL
Topsoil	0	1	
Brown Clay	1	13	
Blue Clay	13	30	
Gravel	30	75	
Blue Clay	75	80	

Date started 8-26-97 Completed 8-26-97

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number 1279
Signed Date 8-29-97

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 514
Signed Date 8-29-97

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER