

RECEIVED LINN 56953

STATE OF OREGON WATER SUPPLY WELL REPORT

(WELL I.D.)# L 80159 (START CARD) # 181925

Instructions for completing this report are on the first page of this form.

WATER RESOURCES DEPT SALEM, OR

(1) OWNER:

Name Coffman Excavation Address P.O. Box 687 / 13014 Clackamas River Dr. City Oregon City State Oregon Zip 97045

well Number 4124

(2) TYPE OF WORK

New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:

Rotary Air Rotary Mud Cable Auger Other

(4) PROPOSED USE:

Domestic Community Industrial Irrigation Thermal Injection Livestock Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes No Depth of Completed Well 68 ft. Explosives used Yes No Type Amount

Table with columns: HOLE Diameter, From, To, Material, SEAL From, To, Sacks or pounds. Row 1: 10, 0, 30, Bentonite, 0, 30, 12 sacks. Row 2: 6, 30, 68.

How was seal placed: Method A B C D E

Other Poured dry

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Casing: 6, +1, 59, 250, checked, unchecked, checked, unchecked. Liner: empty.

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner. Includes checkboxes for Perforations and Screens.

(8) WELL TESTS: Minimum testing time is 1 hour

Table with columns: Pump, Bailer, Air, Flowing Artesian, Yield gal/min, Drawdown, Drill stem at, Time. Values: 40, 68, 1 hr.

Temperature of water 54 Depth Artesian Flow Found Was a water analysis done? Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other Depth of strata:

(9) LOCATION OF WELL by legal description:

County Linn Latitude Longitude Township 12 S Range 3 W WM. Section 7 SW 1/4 NE 1/4 Tax Lot 303 Lot Block Subdivision Street Address of Well (or nearest address) Tangent Dr. Tangent, OR

(10) STATIC WATER LEVEL:

16 ft. below land surface. Date 10/19/2005 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 50

Table with columns: From, To, Estimated Flow Rate, SWL. Row 1: 50, 68, 40, 16.

(12) WELL LOG:

Ground Elevation

Table with columns: Material, From, To, SWL. Rows: Brown clay (0-16), Cemented clay & gravel (16-46), Blue clay (46-50), Cemented gravel (50-61), Blue clay (61-62), Blue cemented sand w/some gravel (62-68).

Date started 10/19/2005 Completed 10/19/2005

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1411 Date 11/04/2005

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1684 Date 11/04/2005