

WELL I.D. # L

(1) LAND OWNER Well Number
 Name Florence M. Cooper
 Address 540 W. 6th Ave.
 City Albany State OR Zip

(2) TYPE OF WORK
 New Well Deepening Alteration (repair/recondition) Abandonment

(3) DRILL METHOD:
 Rotary Air Rotary Mud Cable Auger
 Other

(4) PROPOSED USE:
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other

(5) BORE HOLE CONSTRUCTION:
 Special Construction approval Yes No Depth of Completed Well 32 ft.
 Explosives used Yes No Type Amount

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	

How was seal placed: Method A B C D E
 Other

Backfill placed from ft. to ft. Material
 Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	10	0	32		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Liner:					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used Inside Outside None
 Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

Perforations Method
 Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
24	32					<input checked="" type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>
						<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour

Pump Bailor Air Artesian

Yield gal/min	Drawdown	Drill stem at	Flowing Time
500	8		1 hr.

Temperature of water Depth Artesian Flow Found
 Was a water analysis done? Yes By whom
 Did any strata contain water not suitable for intended use? Too little
 Salty Muddy Odor Colored Other
 Depth of strata:

(9) LOCATION OF WELL by legal description:
 County Linn Latitude Longitude
 Township 10 S N or S Range 4 W E or W. WM.
 Section 1 SW 1/4 NW 1/4
 Tax Lot Lot Block Subdivision
 Street Address of Well (or nearest address)

(10) STATIC WATER LEVEL:
 ft. below land surface. Date
 Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES:

Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG: Ground Elevation

Material	From	To	SWL
No materials listed on registration form. Well drilled by Studabaker Bros. Designated as Pump Well 4 by owner. Nearby wells indicate that well site is underlain by alluvial sediments.			

Date started May 1940 Completed May 1940

SOURCE OF DATA/INFO
Ground Water Registration Certificate GR-791.

COMPILED BY: Karl C. Wozniak

DATE: 10-17-2006