

(9) LOCATION OF WELL by legal description:
County Linn Latitude _____ Longitude _____
Township 10 S N or S Range 1 W E or W. WM.
Section 5 SW 1/4 SW 1/4
Tax Lot _____ Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) _____

(10) STATIC WATER LEVEL:
 _____ ft. below land surface. Date _____
 Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

[illegible]

Date started _____ Completed _____

SOURCE OF DATA/INFO

Water right file G-14931. This is the well described on permit G-13741

COMPILED BY: Karl Wozniak
Groundwater Section.

DATE: June 4, 2014

Stadeli Water Systems, Inc. 503-873-9287

RECEIVED

CCB #124606

JUN 06 2000

**WATER RESOURCES DEPT.
SALEM, OREGON**

P.O. Box 832 • Silverton, OR 97381

WATER WELL TEST REPORT

Date April 15-00 Owner Name Johan Max

Owner Address 39100 Ridge Drive Owner Ph # 503-394-4455

Address of well same Fax # _____

Well type ☒ Irrigation ☒ Domestic ☐ Other _____

Well casing diameter 6" Height of casing above ground surface

Well depth 272' Static water level 155' Well vented yes

Sanitary well seal yes Water sample taken NO

type of sample taken ☐ Purity ☐ Nitrate ☐ Water treatment ☐ Other_____

Existing system used for flow test New Pump Flow measuring device measured container

Description of pump system 5 HP 45 GPM Jacuzzi submersible pump, 1 1/2" Galv
drop pipe, #8-4 subwire, 2 - PC266 Pressure Tanks.

Comments water that was pumped out was clean, very little sediment.

Well flow data collected by Mark Stedeli / Mark Stedeli

Date of flow test April 15 - 00

[illegible]