LINN 60930

STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765 & OAR 690-205-0210)

WELL LABEL # L	112546
START CARD #	1023717

	DITARE CLARE II	
(1) LAND OWNER Owner Well I.D. 5428	(9) LOCATION OF WELL (legal description)	
First Name Ron Last Name Hess	County LINN Twp 14 S N/S Range 1 W E/W	WM
Company	Sec 18 SE 1/4 of the NE 1/4 Tax Lot 1801	Miphemaumauto-
Address 650 Castro Street, #120-292	Tax Map Number Lot	-
City Mountain View State CA Zip 94041	Lat O O DMS or D	
(2) TYPE OF WORK New Well Deepening Conversion	Long On DMS or D	טט
Alteration (repair/recondition) Abandonment		
(3) DRILL METHOD Rotary Air	(10) STATIC WATER LEVEL Date SWL(psi) + SWL(ft)	
(4) PROPOSED USE Domestic X Irrigation Community	Existing Well / Predeepening	
Industrial/ Commercial Livestock Dewatering	Completed Well 07-23-2014 27 Flowing Artesian? Dry Hole?	
Thermal Injection Other		
(5) BORE HOLE CONSTRUCTION Special Standard Attach copy		-
Depth of Completed Well 180 ft.	SWL Date From To Est Flow SWL(psi) + SWL(ft)	ጎ
BORE HOLE SEAL sacks/	07-18-2014 100 125 15 27	\Box
Dia From To Material From To Amt lbs		\dashv
10 0 19 Bentonite 0 19 13 S		-
0 15 180	(11) WELL LOG Ground Elevation	_
How was seal placed: Method A B C D E	Material From To	
▼Other Poured dry	Topsoil 0 2	
Backfill placed from ft. to ft. Material	Brown clay 2 8	_
Filter pack from ft. to ft. Material Size	Small sand and gravel 8 15 Cemented sand & gravel 15 45	_
Explosives used: Yes Type Amount	Cemented sand & gravel 15 45 Gray clay with sand and gravel 45 80	\dashv
(6) CASING/LINER	Cemented sand & gravel 80 119	
Casing Liner Dia + From To Gauge Stl Plstc Wld Thrd	Broken black basalt with gravle 119 125	
	Broken balck basalt w/brown claystone 125 165	
	Weathered basalt 165 170 Gray sandstone w/brown claystone 170 178	\dashv
	Gray basalt 178 180	
Shoe Inside Outside Other Location of shoe(s)	JONES DRILLING CO., INC.	\dashv
Temp casing X Yes Dia 10 From 0 To 19	29400 SANTIAM HWY.	
(7) PERFORATIONS/SCREENS	LEBANON, OR 97355	
Perforations Method Holte air perforator	541-367-2560 541-451-2686	-
Screens Type Material	1-800-915-8388	
Perf/S Casing/Screen Scrn/slot Slot # of Tele/creen Liner Dia From To width length slots pipe size	Date Started 07-17-2014 Completed 07-18-2014	
Perf Casing 6 80 180 .375 .5 500	(unbonded) Water Well Constructor Certification	
178	I certify that the work I performed on the construction, deepening, alteration	
	abandonment of this well is in compliance with Oregon water supply construction standards. Materials used and information reported above are tr	
	the best of my knowledge and belief.	
(8) WELL TESTS: Minimum testing time is 1 hour	License Number 1888 Date 07-24-2014	_
Pump Bailer Air Flowing Artesian	Password : (if filing electronically) Signed	_
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr) 20 179 1	(bonded) Water Well Constructor Certification	
	I accept responsibility for the construction, deepening, alteration, or abando	nment
	work performed on this well during the construction dates reported above. Al	ll work
Temperature 53 °F Lab analysis Yes By	performed during this time is in compliance with Oregon water supply	y well
Water quality control E VED (Byrio halps) From To Description E IVE Dubing Outlise D	construction standards. This report is true to the best of my knowledge and be	enet.
Prom To Description C V Amount Outs	License Number 1684 Date 07.24-2014	
JUL 2 9 2014	Password : (1) filing electronically) Signed	
SEP 1 2 2014	Contact Info (optional) jon-sdrilling@hotmail.com	