

STATE OF OREGON
WATER SUPPLY WELL REPORT

(as required by ORS 537.765 & OAR 690-205-0210)

WELL I.D. LABEL# L	119455
START CARD #	1028198
ORIGINAL LOG #	LINN 53597

(1) LAND OWNER Owner Well I.D. 5579
 First Name Roger Last Name Ruckert
 Company _____
 Address 33776 Ridge Dr.
 City Tangent State OR Zip 97389

(2) TYPE OF WORK New Well Deepening Conversion
 Alteration (complete 2a & 10) Abandonment (complete 5a)

(2a) PRE-ALTERATION
 Casing:

Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd

 Seal:

Material	From	To	Amt	sacks/lbs

(3) DRILL METHOD
 Rotary Air Rotary Mud Cable Auger Cable Mud
 Reverse Rotary Other _____

(4) PROPOSED USE Domestic Irrigation Community
 Industrial/ Commercial Livestock Dewatering
 Thermal Injection Other _____

(5) BORE HOLE CONSTRUCTION Special Standard (Attach copy)
 Depth of Completed Well 180 ft.

BORE HOLE			SEAL			sacks/lbs
Dia	From	To	Material	From	To	Amt
10	110	180	undisturbed			
						Calculated
						Calculated

How was seal placed: Method A B C D E
 Other _____
 Backfill placed from _____ ft. to _____ ft. Material _____
 Filter pack from _____ ft. to _____ ft. Material _____ Size _____
 Explosives used: Yes Type _____ Amount _____

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
 Proposed Amount _____ Pounds Actual Amount _____ Pounds

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd

 Shoe Inside Outside Other Location of shoe(s) _____
 Temp casing Yes Dia _____ From _____ To _____

(7) PERFORATIONS/SCREENS
 Perforations Method _____
 Screens Type _____ Material _____

Perf/S	Casing/Screen	Scrn/slot	Slot	# of	Tele/			
green	Liner	Dia	From	To	width	length	slots	pipe size

(8) WELL TESTS: Minimum testing time is 1 hour
 Pump Bailer Air Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
225		179	1

 Temperature 52 °F Lab analysis Yes By _____
 Water quality concerns? Yes (describe below) TDS amount 164

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)
 County LINN Twp 12 S N/S Range 3 W E/W WM
 Sec 27 NW 1/4 of the NE 1/4 Tax Lot 100
 Tax Map Number _____ Lot _____
 Lat _____ " or _____ DMS or DD
 Long _____ " or _____ DMS or DD
 Street address of well Nearest address
33776 Ridge Dr., Tangent, OR 97389

(10) STATIC WATER LEVEL

Existing Well / Pre-Alteration	Date	SWL (psi)	+ SWL (ft)
Completed Well	09-16-2015		28

 Flowing Artesian? Dry Hole?
 WATER BEARING ZONES Depth water was first found 110

SWL Date	From	To	Est Flow	SWL (psi)	+ SWL (ft)
09-16-2015	110	114	225	28	28

(11) WELL LOG Ground Elevation _____

Material	From	To
Previously drilled	0	110
Blue sandy & gravel	110	114
Gray clay	114	114
Black sand	114	120
Gray clay with black sand strips	120	180

 RECEIVED BY OWRD
JONES DRILLING CO., INC.
29400 SANTIAM HWY. SEP 28 2015
LEBANON, OR 97355
541-367-2560 541-451-2686
1-800-915-8388 SALEM, OR

Date Started 09-16-2015 Completed 09-16-2015
(unbonded) Water Well Constructor Certification
 I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
 License Number 1888 Date 09-22-2015
 Signed [Signature]
(bonded) Water Well Constructor Certification
 I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
 License Number 1684 Date 09-22-2015
 Signed [Signature]
 Contact Info (optional) jonesdrilling@hotmail.com