LINN 63086

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

WELL I.D. LABEL# L		
START CARD #	1045002	
ORIGINAL LOG#	binn	4219

(1) LAND OWNER Owner Well I.D. 6062		
First Name Amy Last Name Doerfler	(9) LOCATION OF WELL (legal description)	
Company K2A Properties	County LINN Twp 10 S N/S Range 2 W E/W WM	
Address 12333 Silver Falls Hwy. SE	Sec 20 NW 1/4 of the NW 1/4 Tax Lot 300	
City Aumsville State OR Zip 97325	Tax Map Number Lot	
(2) TYPE OF WORK New Well Deepening Conversion	Tax Map Number Lot Lat " or DMS or DD	
Alteration (complete 2a & 10) X Abandonment(complete 5a)	Long " " or DMS or DD	
(2a) PRE-ALTERATION Dia + From To Gauge Stl Plstc Wld Thrd	Lat°' or DMS or DD Long° '" or DMS or DD O Street address of well Nearest address	
Casing:		
Material From To Amt sacks/lbs	3833 Densmore Rd Jefferson, OR 97352	
Seal:		
(3) DRILL METHOD	(10) STATIC WATER LEVEL	
Rotary Air Rotary Mud Cable Auger Cable Mud	Date SWL(psi) + SWL(ft) Existing Well / Pre-Alteration	
Reverse Rotary Other	Completed Well	
(4) PROPOSED USE Domestic Irrigation Community	Flowing Artesian? Dry Hole?	
Industrial/ Commercial Livestock Dewatering		
Thermal Injection Other	WATER BEARING ZONES Depth water was first found	
	SWL Date From To Est Flow SWL(psi) + SWL(ft)	
(5) BORE HOLE CONSTRUCTION Special Standard (Attach copy)		
Depth of Completed Well 0 ft.		
BORE HOLE SEAL sacks/		
Dia From To Material From To Amt lbs 10 0 30 Cement 0 30 59 S		
Calculated 11	·	
	20 HM 1 100	
Calculated	(11) WELL LOG Ground Elevation	
How was seal placed: Method A B XC D E	Material From To	
Other	Cut 10" casing 2' below grade	
Backfill placed from ft. to ft. Material	RECEIVED	
Filter pack from ft. to ft. Material Size	RECEIVED	
Explosives used: Yes Type Amount		
(5a) ABANDONMENT USING UNHYDRATED BENTONITE	APR 2.7 2020	
Proposed Amount Pounds Actual Amount Pounds		
(6) CASING/LINER Casing Liner Dia + From To Gauge Stl Plstc Wld Thrd	OWRD	
	TOMES BRILLING SO. INS	
	JONES DRILLING CO., INC.	
	29400 SANTIAM HWY.	
	LEBANON, OR 97355	
Shoe Inside Outside Other Location of shoe(s)	541-367-2560 541-451-2686	
Temp casing Yes Dia From To		
(7) PERFORATIONS/SCREENS	1-800-915-8388	
Perforations Method		
Screens Type Material	Date Started <u>04-13-2020</u> Completed <u>04-14-2020</u>	
Perf/S Casing/ Screen Scrn/slot Slot # of Tele/ creen Liner Dia From To width length slots pipe size	(unbonded) Water Well Constructor Certification	
creen Liner Dia From To width length slots pipe size	I certify that the work I performed on the construction, deepening, alteration, or	
	abandonment of this well is in compliance with Oregon water supply well	
	construction standards. Materials used and information reported above are true to	
	the best of my knowledge and belief.	
	License Number 141+ 1888 Date 0420-2020	
(8) WELL TESTS: Minimum testing time is 1 hour	Signed	
Pump Bailer Air Flowing Artesian	- William	
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)	(bonded) Water Well Constructor Certification	
	I accept responsibility for the construction, deepening, alteration, or abandonment	
	work performed on this well during the construction dates reported above. All work	
<u> </u>	performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.	
Temperature °F Lab analysisYes By	1	
Water quality concerns? Yes (describe below) TDS amount From To Description Amount Units	License Number 1684 Date 04-20-2020	
100 Description Timoun Onto	Signed //	
	Contact Into (opponal) joneschiling@hotmail.com	
	· '// //	