#9

MALH 2588

Malh 2588

G-12609

16S/43E/14da

(START CARD) # 22417

STATE OF OREGON

WATER WELL REPORT

(as required by ORS 537.765)

(1) OWNER:

Well Number: 22417

Name Y1 Farms Inc

Address 5112 Maag Rd

City Vale State OR Zip 97918

(2) TYPE OF WORK:

☑ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☑ Cable

☐ Other

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation

☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes ☐ No ☑ Depth of Completed Well 60 ft.

Explosives used Yes ☐ No ☑ Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
20"	0	20 ft	Cement Grout	0	20 ft	~~30~~ 40
16"	0	60'				

How was seal placed: Method ☐ A ☐ B ☑ C ☐ D ☐ E

☐ Other

Backfill placed from ~~35~~ ft. to ~~20~~ ft. Material

Gravel placed from 35 ft. to 20 ft. Size of gravel 1½

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	16	+1	36	.250	☑	☐	☑	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) 36 ft

(7) PERFORATIONS/SCREENS:

☑ Perforations Method torch

☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
~~25~~	~~35~~	6"	325	1/4	16"	☑	☐
23	35					☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☑ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	~~Drill~~ Pump stem at	Time
400	19 ft	47	1 hr.
			4 hrs

Temperature of water 61° Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County Malheur Latitude Longitude

Township 16 S N or S. Range 43 E E or W, WM.

Section 14 NE ¼ SE ¼

Tax Lot 1502 Lot Block Subdivision

Street Address of Well (or nearest address) 5112 Maag Rd

(10) STATIC WATER LEVEL:

10 ft. below land surface. Date 4-14-91

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 23 ft

From	To	Estimated Flow Rate	SWL
23	35	400	10 ft

(12) WELL LOG:

Ground elevation

Material	From	To	SWL
topsoil	0	4	
Brown clay	4	23	
large gravel	23	35	10
Blue clay	35	60	10

RECEIVED

APR 26 1991

WATER RESOURCES DEPT.

SALEM, OREGON

Date started 4-9-91 Completed 4-14-91

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1485

Signed Jon M Fife Date 4-16-91

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88