a

RECEIVED

MAR 30 1992

MALH 2725

165/43E/13CC

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

(START CARD) # 79825

(1) OWNER:
Well Number: 29825
Name: Joseph L Arriola
Address: 2506-12th Ave East
City: Vale State: OR Zip: 97918

(2) TYPE OF WORK:
☑ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☑ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No ☑ Depth of Completed Well 70 ft.
Explosives used Yes ☐ No ☑ Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
16	0	27	Cement	0	18	22
12	0	70	grout			

How was seal placed: Method ☐ A ☐ B ☑ C ☐ D ☐ E
☐ Other
Backfill placed from ft. to ft. Material
Gravel placed from 18 ft. to 27 ft. Size of gravel 1½

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	12"	+1	43	.250	☑	☐	☑	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s) 43 ft

(7) PERFORATIONS/SCREENS:
☑ Perforations Method torch
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
25	41	6"	250	5/16	12"	☑	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☑ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
350	18 ft	42	1 hr.
			4 hrs

Temperature of water 59° Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Malheur Latitude ' " Longitude ' "
Township 16 S ☒ or S, Range 43 E E or ~~W, WM.~~
Section 13 SW ¼ SW ¼
Tax Lot 1500 Lot Block Subdivision
Street Address of Well (or nearest address) 2506 12th Ave E
Vale, OR

(10) STATIC WATER LEVEL:
17'-10" ft. below land surface. Date 3-6-92
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found

From	To	Estimated Flow Rate	SWL
27	36		17-10

(12) WELL LOG:
Ground elevation

Material	From	To	SWL
Sandy topsoil	0	4	
Brown clay	4	27	
large clean gravel	27	36	17'-10"
Brown clay	36	37	
Blue clay	37	60	17-10

Date started 2-29-92 Completed 3-6-92

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 1485
Signed Jon M Fife Date 3-25-92

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88