MALH 51186

APR 21 1999

L-24167

WATER RESOURCES DEPT. SALEM, OREGON

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

WELL I.D.# 66049

(1) OWNER: Well Number 66049

Name Malheur County

Address 251 B St. W-#1

City Vale State Ore Zip 97918

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:

[ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger

[ ] Other

(4) PROPOSED USE:

[ ] Domestic [ ] Community [ ] Industrial [X] Irrigation

[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval [ ] Yes [X] No Depth of Completed Well 43 ft.

Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
16	0	20	Bentonite	0	18	38 SACKS
8	20	43				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[ ] Other Bentonite poured & Tamped

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	8"	+1	38	250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) 38'

(7) PERFORATIONS/SCREENS:

[X] Perforations Method Torch

[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
-28	-38	1/4x6	60	8		[X]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour

[ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
30	-0-		1 hr.

Temperature of water Depth Artesian Flow Found

Was a water analysis done? [ ] Yes By whom

Did any strata contain water not suitable for intended use? [ ] Too little

[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County Malheur Latitude Longitude

Township 18 (N) or S Range 47 (E) or W. WM.

Section 9 S.E. 1/4 S.E. 1/4

Tax Lot 603 Lot Block Subdivision

Street Address of Well (or nearest address) S.W. 4th St Ontario Ore. 97914

(10) STATIC WATER LEVEL:

20 ft. below land surface. Date 7-21-98

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 22

From	To	Estimated Flow Rate	SWL
22	38'		20'

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
	~~0~~	~~5~~	
Top Soil	0	5	
Sandy Brown Clay	5	16	
Sand & Gravel	16	38	20'
Blue Clay	38	43	

RECEIVED

MAR 15 1999

WATER RESOURCES DEPT. SALEM, OREGON

Date started 7-2-98 Completed 7-21-98

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1470

Signed Dennis Page Date 2-14-99

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER