STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

MALH 54399

11/6/2017

WELL I.D. LABEL# L
START CARD # 187382
ORIGINAL LOG #

(1) LAND OWNER

Owner Well I.D.
First Name GEORGE Last Name RODRIGUEZ
Company
Address 213 BOAT LANDING RD
City ONTARIO State OR Zip 97914

(2) TYPE OF WORK

☐ New Well ☐ Deepening ☐ Conversion
☐ Alteration (complete 2a & 10) ☒ Abandonment(complete 5a)

(2a) PRE-ALTERATION

	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
Casing:						○	○	☐	☐

	Material	From	To	Amt	sacks/lbs
Seal:					

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☒ Other DRY POUR

(4) PROPOSED USE

☒ Domestic ☐ Irrigation ☐ Community
☐ Industrial/ Commericial ☐ Livestock ☐ Dewatering
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION

Special Standard ☒ (Attach copy)
Depth of Completed Well 0.00 ft.

BORE HOLE Dia	From	To	SEAL Material	From	To	Amt	sacks/lbs
					Calculated		
					Calculated		

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other DRY POUR
Backfill placed from ____ ft. to ____ ft. Material ____
Filter pack from ____ ft. to ____ ft. Material ____ Size ____
Explosives used: ☐ Yes Type ____ Amount ____

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount 11.00 Sacks Actual Amount 10.50 Sacks

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐

Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s) ____
Temp casing ☐ Yes Dia ____ From + ☐ ____ To ____

(7) PERFORATIONS/SCREENS

Perforations Method ____
Screens Type ____ Material ____

Perf/ Screen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size

(8) WELL TESTS: Minimum testing time is 1 hour

○ Pump ○ Bailer ○ Air ○ Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)

Temperature ____ °F Lab analysis ☐ Yes By ____
Water quality concerns? ☐ Yes (describe below) TDS amount 609 ppm

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County MALHEUR Twp 17.00 S N/S Range 47.00 E E/W WM
Sec 15 NE 1/4 of the NE 1/4 Tax Lot 100
Tax Map Number ____ Lot ____
Lat ___° ___' ___" or 44.09694444 DMS or DD
Long ___° ___' ___" or -116.94638889 DMS or DD
○ Street address of well ◉ Nearest address
211 BOAT LANDING RD

(10) STATIC WATER LEVEL

	Date	SWL(psi)	+	SWL(ft)
Existing Well / Pre-Alteration	7/20/2017		☐	10
Completed Well			☐	

Flowing Artesian? ☐ Dry Hole? ☐

WATER BEARING ZONES Depth water was first found ____

SWL Date	From	To	Est Flow	SWL(psi)	+	SWL(ft)

(11) WELL LOG

Ground Elevation 2137.00

Material	From	To

Date Started 7/20/2017 Completed 7/20/2017

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number ____ Date ____

Signed ____

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1481 Date 11/6/2017

Signed MARVIN G HAINES (E-filed)

Contact Info (optional) Marvin Haines # 1481