

**NOTICE TO WATER WELL CONTRACTOR**

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

**WATER WELL REPORT**

STATE OF OREGON  
(Please type or print)

State Well No. 9/26-6L2  
State Permit No. \_\_\_\_\_

**(1) OWNER:**

Name DERAL JONES  
Address 1095 LIBERTY N.E.  
SALEM ORE

**(2) LOCATION OF WELL:**

County MARION Driller's well number \_\_\_\_\_  
1/4 1/4 Section 6 T. 9S R. 2W W.M.  
Bearing and distance from section or subdivision corner \_\_\_\_\_

**(3) TYPE OF WORK (check):**

Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐  
abandonment, describe material and procedure in Item 12.

**(4) PROPOSED USE (check):**

Domestic ☒ Industrial ☐ Municipal ☐  
Irrigation ☐ Test Well ☐ Other ☐

**(5) TYPE OF WELL:**

Rotary ☒ Driven ☐  
Cable ☐ Jetted ☐  
Dug ☐ Bored ☐

**(6) CASING INSTALLED:**

Threaded ☐ Welded ☒

6" Diam. from 0 ft. to 46' ft. Gage 17.02  
" Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Gage \_\_\_\_\_  
" Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Gage \_\_\_\_\_

**(7) PERFORATIONS:**

Perforated? ☐ Yes ☒ No

Type of perforator used \_\_\_\_\_

| Size of perforations    | in. | by       | in. |
|-------------------------|-----|----------|-----|
| perforations from _____ | ft. | to _____ | ft. |
| perforations from _____ | ft. | to _____ | ft. |
| perforations from _____ | ft. | to _____ | ft. |
| perforations from _____ | ft. | to _____ | ft. |
| perforations from _____ | ft. | to _____ | ft. |

**(8) SCREENS:**

Well screen installed? ☐ Yes ☒ No

Manufacturer's Name \_\_\_\_\_  
pe \_\_\_\_\_ Model No. \_\_\_\_\_  
Diam. \_\_\_\_\_ Slot size \_\_\_\_\_ Set from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Diam. \_\_\_\_\_ Slot size \_\_\_\_\_ Set from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

**(9) CONSTRUCTION:**

Well seal—Material used in seal BENTONITE  
Depth of seal 46' ft. Was a packer used? yes  
Diameter of well bore to bottom of seal 10" in.  
Were any loose strata cemented off? ☐ Yes ☒ No Depth \_\_\_\_\_  
Was a drive shoe used? ☐ Yes ☒ No  
Was well gravel packed? ☐ Yes ☒ No Size of gravel: \_\_\_\_\_  
Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Did any strata contain unusable water? ☐ Yes ☒ No  
Type of water? \_\_\_\_\_ Depth of strata \_\_\_\_\_  
Method of sealing strata off \_\_\_\_\_

**(10) WATER LEVELS:**

Static level 33' 6" ft. below land surface Date 8-7-65  
Artesian pressure \_\_\_\_\_ lbs. per square inch Date \_\_\_\_\_

**(11) WELL TESTS:**

Drawdown is amount water level is lowered below static level SNEED  
Was a pump test made? ☒ Yes ☐ No If yes, by whom? BRAS

Yield: 23 gal./min. with 58 ft. drawdown after 2 hrs.  
" " " "  
" " " "  
" " " "  
" " " "

Ballor test gal./min. with \_\_\_\_\_ ft. drawdown after \_\_\_\_\_ hrs.  
Artesian flow g.p.m. Date \_\_\_\_\_  
Temperature of water 54° Was a chemical analysis made? ☐ Yes ☒ No

**(12) WELL LOG:**

Diameter of well below casing 6"

Depth drilled 128' ft. Depth of completed well 128' ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

| MATERIAL       | FROM | TO  |
|----------------|------|-----|
| TOPSOIL        | 0    | 1   |
| RED CLAY       | 1    | 4   |
| BOULDERS 4'-   | 4    | 55' |
| BASALT CREVICY | 45   | 128 |

**RECEIVED**  
AUG 16 1965  
STATE ENGINEER  
SALEM OREGON

Work started 8-4 1965 Completed 8-7 1965  
Date well drilling machine moved off of well 8-7 1965

**(13) PUMP:**

Manufacturer's Name Reported  
Type: Sub H.P. 2 H.P.

**Water Well Contractor's Certification:**

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME J. A. SNEED & SONS  
(Person, firm or corporation) (Type or print)  
Address 3910 SILVERTON RD. SALEM, O.

Drilling Machine Operator's License No. 187

[Signed] B. J. Sneed  
(Water Well Contractor)

Contractor's License No. 6 Date 8-7, 1965