RECEIVED MAR... JUN 5 1963 STATE ENGINEER SALEM, OREGON

15372

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

State Well No. 9/3W-33B

State Permit No.

(1) OWNER:
Name L. C. Ebertson
Address N. E. Cleveland Ave
Gatland Oregon

(2) LOCATION OF WELL:
County Marion Driller's well number 9
~~SW~~ ¼ ~~SE~~ ¼ Section 33 T. 9 S R. 3 W W.M.
Name and distance from section or subdivision corner NW NE

(3) TYPE OF WORK (check):
New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☐ Municipal ☐
Irrigation ☒ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒
8" Diam. from 10" + ft. to 27½ ft. Gage 250
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☒ Yes ☐ No
Type of perforator used torch
Size of perforations ¾ + ½ in. by 9 in.
23 perforations from 23 ft. to 26½ ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☒ No
Manufacturer's Name
Type Model No.
Diam. X Slot size X Set from X ft. to X ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal Silt + Clay
Depth of seal 16 ft. Was a packer used?
Diameter of well bore to bottom of seal 10 in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☐ Yes ☐ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel: X
Gravel placed from X ft. to X ft. X
Did any strata contain unusable water? ☐ Yes ☐ No
Type of water? River Depth of strata 16 to 27½
Method of sealing strata off

(10) WATER LEVELS:
Static level 5 ft. below land surface Date 5-23
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☐ No If yes, by whom?
Yield: 600 gal./min. with 2 ft. drawdown after 2 hrs.
" " " "
" " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 56 Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well below casing 8"
Depth drilled 27½ ft. Depth of completed well 27½ ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Surface + Silt	0	3
Silt + Clay Yellow	3	16
River Run Gravel	16	27½
Clay Yellow	27½	

Work started 5-22 1963 Completed 5-23 1963
Date well drilling machine moved off of well 5-23 1963

(13) PUMP:
Manufacturer's Name
Type: Centrifugal H.P. 7½

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
NAME Ace Drilling Co. (Person, firm or corporation) (Type or print)
Address Albany Oregon
Drilling Machine Operator's License No. 285
[Signed] Bill Hamilton (Water Well Contractor)
Contractor's License No. 52 Date 5-23, 1963

(USE ADDITIONAL SHEETS IF NECESSARY)