

JUL 01 1991

MAR 17 3 42

7S/2W/26 dc

STATE OF OREGON WATER WELL REPORT WATER RESOURCES DEPT SALEM, OREGON

(START CARD) # 25459

(1) OWNER: Name Gary Kaufman Address PO Box 3154 City Salem State OR Zip 97302

(9) LOCATION OF WELL by legal description: County Marion Township 7S Section 26 Tax Lot 26

(2) TYPE OF WORK: [X] Deepen [ ] Recondition [ ] Abandon

(3) DRILL METHOD: [X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Other

(10) STATIC WATER LEVEL: 44 ft. below land surface. Date 5-9-91

(4) PROPOSED USE: [ ] Domestic [ ] Community [ ] Industrial [X] Irrigation [ ] Thermal [ ] Injection [ ] Other

(11) WATER BEARING ZONES: Depth at which water was first found

(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well 490 ft.

Table with 4 columns: From, To, Estimated Flow Rate, SWL. Row 1: 451, 454, 250 gpm, 44

Table with 4 columns: HOLE Diameter, SEAL From, SEAL To, Amount sacks or pounds. Row 1: 10", 300, 490

(12) WELL LOG: Ground elevation

How was seal placed: Method [X] A [ ] B [ ] C [ ] D [ ] E [ ] Other

Table with 4 columns: Material, From, To, SWL. Rows: Basalt black hard (408-451), Basalt black broken (451-454), Basalt black hard (454-463), Basalt grey very hard (463-490)

(6) CASING/LINER: Table with columns for Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

(7) PERFORATIONS/SCREENS: [ ] Perforations [ ] Screens Method Type Material

Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

Date started 5-3-91 Completed 5-9-91

(8) WELL TESTS: Minimum testing time is 1 hour [ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards.

Temperature of water 54 Depth Artesian Flow Found Was a water analysis done? [ ] Yes By whom

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above.