

16

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

MAR 1 18332

RECEIVED

MAR 15 1993

83/2w/27 (START CARD) # 50058

(1) OWNER: Name Walt Miller, Well Number 2554, Address P.O. Box 12395, City Salem, State OR, Zip 97309

(9) LOCATION OF WELL by legal description: County Marion, Township 8, Range 2, Section 27, Street Address of Well (or nearest address) E. of Turner 2 miles

(2) TYPE OF WORK: [X] New Well, [] Deepen, [] Recondition, [] Abandon

(10) STATIC WATER LEVEL: 9 1/2 ft. below land surface, Date 3/3/93

(3) DRILL METHOD: [X] Rotary Air, [] Rotary Mud, [] Cable, [] Other

(11) WATER BEARING ZONES: Depth at which water was first found 83

(4) PROPOSED USE: [] Domestic, [] Community, [] Industrial, [X] Irrigation, [] Thermal, [] Injection, [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No, Depth of Completed Well 56.5 ft., Explosives used [] Yes [X] No

Table with 4 columns: From, To, Estimated Flow Rate, SWL. Row 1: 83, 56.5, 300 gpm, 9 1/2

Table with 4 columns: HOLE Diameter, SEAL Material, Amount. Row 1: 12, 0.58, Cement, 37 sacks

(12) WELL LOG: Ground elevation

How was seal placed: Method [] A [] B [X] C [] D [] E, Backfill placed from ft. to ft. Material, Gravel placed from ft. to ft. Size of gravel

Table with 4 columns: Material, From, To, SWL. Rows include Topsoil, Sandy Gravel, Blue Clay, Blue Basalt

(6) CASING/LINER: Table with columns for Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: [] Perforations, [] Screens

Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour. [] Pump, [] Bailer, [X] Air, [] Flowing Artesian. Yield 300 gpm, Drawdown, Drill stem at 56.5, Time 1 hr.

Date started 2/26/93, Completed 3/3/93. (unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards.

Temperature of Water 56, Depth Artesian Flow Found X, Was a water analysis done? [] Yes By whom, Did any strata contain water not suitable for intended use? [] Too little, [] Salty, [] Muddy, [] Odor, [] Colored, [] Other

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards.