

RECEIVED

MARI... 2/160

55/1W-34dd

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

APR 27 1987

(1) OWNER: Chris & Joe Bachler, SALEM, OREGON

(2) LOCATION OF WELL by legal description: Marion County, SS Township, 1W N or S, Range, 34 Section, SE 1/4 SE 1/4

(2) TYPE OF WORK: [X] New Well, [ ] Deepen, [ ] Recondition, [ ] Abandon

(3) DRILL METHOD: [ ] Rotary Air, [ ] Rotary Mud, [X] Cable, [ ] Other

(10) STATIC WATER LEVEL: 87 ft. below land surface. Date 4/11/87

(4) PROPOSED USE: [ ] Domestic, [ ] Community, [ ] Industrial, [X] Irrigation

(11) WELL LOG: Ground elevation

(5) BORE HOLE CONSTRUCTION: Depth of Completed Well 688 ft.

Table with columns: HOLE Diameter, From, To, Material, SEAL From, To, Amount sacks or pounds

WELL LOG table with columns: Material, From, To, WB?, SWL

How was seal placed? Method [ ] A [ ] B [ ] C [ ] D [ ] E [X] Other 690-210-340

(6) CASING/LINER: Diameter 12", From +2, To 379, Gauge 350

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour. Yield 70 gal/min, Pumping level 172, Drill stem at 195

Date started 2/24/87 Completed 4/10/87

(unbonded) Water Well Constructor Certification: I constructed this well in compliance with Oregon well construction standards.

Signed [Signature] Date 4/16/87

(bonded) Water Well Constructor Certification: I accept responsibility for construction of this well and its compliance with all Oregon water well standards.

Signed [Signature] Date 4/16/87

Company Grossen's Well Drilling Co. Job No. 71