STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

RECEIVED SEP 15 1988 WATER RESOURCES DEPT. SALEM, OREGON

MART....5098 6S/3W/24 ab Record

(1) OWNER:
Well Number:
Name Boltman's Nursery
Address 8375 River Rd. NE
City Salem State Ore. Zip 97303

(2) TYPE OF WORK:
☐ New Well ☐ Deepen ☑ Recondition ☐ Abandon

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No ☐ Depth of Completed Well ____ ft.
Explosives used Yes ☐ No ☐ Type ____ Amount ____

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other
Backfill placed from ____ ft. to ____ ft. Material
Gravel placed from ____ ft. to ____ ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	7"	+1'	81'	.125	☑	☐	☑	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Perforated from ____ to ____ location of shoe(s)

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type ____ Material

Perforated from	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
			1 hr.

Temperature of water ____ Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Marion Latitude ____ ' ____ " Longitude ____ ' ____ "
Township 6S N or S, Range 3W E or W, WM.
Section 24 NW NE ¼
Tax Lot ____ Lot ____ Block ____ Subdivision
Street Address of Well (or nearest address) 8375 River Rd. NE

(10) STATIC WATER LEVEL:
35 ft. below land surface. Date 6-13-88
Artesian pressure ____ lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:
Ground elevation

Material	From	To	SWL
Liner was installed in this existing 97'-8" well. The liner has a neoprene conical packer at the bottom to seal off sand entering from a perforated zone 75'-88'.			

Date started June 3, 1988 Completed June 13, 1988

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 633
Signed Michael Waldroop Date 7-5-88

WHITE COPIES - WATER RESOURCES DEPARTMENT YELLOW COPY - CONSTRUCTOR PINK COPY - CUSTOMER 9809C 10/86