## MARI RECEIVED

51527

MAR 2 7 1997 WELL

LO2414

STATE OF OREGON

WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WATER RESOURCES DEPT.

(START CARD) #	78624/4279

Instructions for completing this report are on the last page of thatem, OREGON (9) LOCATION OF WELL by legal description: (1) OWNER: Well Number County Marion Latitude Longitude Valentine Miller E or W. WM. N or S Range 8626 Wabash Dr.NE Township Zip 97305 SE 36 NW 1/4 1/4 **Brooks** City 00300 LotSubdivision Block (2) TYPE OF WORK 8626 Wabash Dr.NE Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment Brooks, OR (3) DRILL METHOD: (10) STATIC WATER LEVEL: Auger Rotary Air Rotary Mud Cable Date 2/28/97 31 ft. below land surface. Other Artesian pressure lb. per square inch. (4) PROPOSED USE: (11) WATER BEARING ZONES: \*Irrigation Industrial Domestic Community Other Livestock Thermal Injection Depth at which water was first found (5) BORE HOLE CONSTRUCTION: Special Construction approval XYes No Depth of Completed Well 233 ft. Estimated Flow Rate Explosives used Yes No Type SEAL HOLE Sacks or pounds To Material Diameter From portland 112 132 9sacks cement (12) WELL LOG:  $\square$ B Ground Elevation Method A How was seal placed: Special standards **SWL** From Material Material ft. to Backfill placed from Well was perforated from 122 127 ft. to Size of gravel Gravel placed from and 10" pvc sch.40 pipe was (6) CASING/LINER: installed and pressure grouted Welded Threaded Gauge Steel To Diameter from 112' to 132' 1.32 sch40 Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Method Perforations Material Screens Type Tele/pipe Casing Number 36 Liner Diameter 122 127° Completed 2/28/97 Date started 2/21/97 (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Artesian ☐ Air of this well is in compliance with Oregon water supply well construction standards.

Materials used and information reported above are true to the best of my knowledge Pump ☐ Bailer Drill stem at Time Drawdown Yield gal/min WWC Number Date Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? Yes By whom performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Salty Muddy Odor Colored Other WWC Number 783 Depth of strata: Date 3/24/97