

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

APR 16 1997

WELL I.D.#

WATER RESOURCES DEPT.

51693

(START CARD) # 85415

Instructions for completing this report are on SALEM OREGON form.

(1) OWNER:

Name PRO-CONSTRUCT, INC. Well Number _____
Address P.O. Box 12397
City Salem State ore. Zip 97309

(2) TYPE OF WORK

☐ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☒ Abandonment

(3) DRILL METHOD:

☐ Rotary Air ☐ Rotary Mud ☒ Cable ☐ Auger
☐ Other _____

(4) PROPOSED USE:

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☐ No Depth of Completed Well _____ ft.

Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	
			N/A			

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☐ Other _____

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
Liner:					☐	☐	☐	☐

Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:

		Method		Type		Material	
From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump	☐ Bailer	☐ Air	☒ Flowing Artesian
Yield gal/min	Drawdown	Drill stem at	Time
			1 hr.
N/A			

Temperature of water _____ Depth Artesian Flow Found _____

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____

Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County Marion Latitude _____ Longitude _____
Township 7S N or S Range 2W E or W. WM.
Section 29 SW 1/4 SW 1/4
Tax Lot 800 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 4725 State St.
Salem, Ore.

(10) STATIC WATER LEVEL:

9 ft. below land surface. Date 4-4-97
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:

Ground Elevation _____

Material	From	To	SWL
WELL DATA: <u>38 ft. deep 6" diameter well cased w/ Thread + coupled pipe</u>			
ABANDONMENT PROCEDURE			
The pipe above ground was hit & bent w/ an excavating machine.			
A crawler was used to straighten the pipe to vertical position. Due to the side play back & forth, the joint at 10' was weakened & when pulled, came apart.			
Special Standards were given to use bentonite in the latter 20' which could not be perforated. Cement was used in the remainder from 20' - ground level after perforating from 20' - 10'. 200 sacks of bentonite (3/8") from 20' - 20' + 18 sacks cement used to fill from 20' - 2' Bentonite (2 sacks) topped hole to surface.			
Date started <u>4-4-97</u> Completed <u>4-4-97</u>			

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number _____

Signed _____ Date _____

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 633

Signed Michael Waldrop Date 4-4-97