

RECEIVED

AUG 19 1998

MARI 53258

STATE OF OREGON WATER SUPPLY WELL REPORT WATER RESOURCES DEPT. (as required by ORS 537.765) SALEM, OREGON

WELL I.D. #L 24468 START CARD # 104383

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 3282 Name Imperial Garden Address 11650 Goody Garden Ln City Woodburn State OR Zip 97071

(2) TYPE OF WORK [X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [X] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [] No Depth of Completed Well 131 ft. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE, SEAL, Diameter, From, To, Material, From, To, Sacks or pounds. Includes entries for 10" and 6" diameters with Bent. material.

How was seal placed: Method [] A [] B [] C [] D [] E [X] Other Poured from Top Backfill placed from ft. to ft. Material Gravel placed from ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Includes entries for 6" casing and liner.

Final location of shoe(s) 131

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner. Includes entry for 127-131 slot size.

(8) WELL TESTS: Minimum testing time is 1 hour [X] Pump [] Bailer [X] Air [] Artesian Yield gal/min 5.5 gpm Drawdown 10 ft dcl Time 1 hr.

Temperature of water 53 Depth Artesian Flow Found Was a water analysis done? No Yes By whom Did any strata contain water not suitable for intended use? [X] Too little [] Salty [] Muddy [] Odor [] Colored [X] Other Sandy Depth of strata: 45-125

(9) LOCATION OF WELL by legal description: County Marion Latitude Longitude Township 55 N or S Range 1 W E or W. WM. Section 4 SW 1/4 SW 1/4 Tax Lot 01100 Lot Block Subdivision Street Address of Well (or nearest address) Same as above

(10) STATIC WATER LEVEL: 54 ft. below land surface. Date 8/12/98 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 45

Table with columns: From, To, Estimated Flow Rate, SWL. Includes entries for 45-89 and 101-131.

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Includes entries for Top Soil, Brown Clay, Grey Sandy Clay, Black Sand, Blue Clay, Black Sand, Black Sandy Gravel, Black Sand + Gravel, Grey Clay.

Date started 8/12/98 Completed 8/12/98

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Dallas J. Davis WWC Number 561 Date 8/15/98

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Dallas J. Davis WWC Number 561 Date 8/15/98