STATE OF OREGON WATER SUPPLY WELL REPORT (ess required by ORS 537.765) Instructions for completing this report are on the last page of this form

MARI 56141 WELL ID# **L46709**

OTADT	CADD\ #	141484

(1) OWNER:		Well Number:	740	(9) LOCATION OF	WELL by legal de	scription:	
Name Address 13971 Wisky Hill Rd. City Hubbard State OR Zip 97032				County Marion Township 3S	N or S. Range 1W	atitude Longitude E or W. of	
				Section 33 SW % SE %			
		, Jose OIV	cip orooz	Tax Lot 1500	Lot Block	Subdivision	
(2) TYPE OF \				Street Address of We 12012 Arndt Rd		Condition to the second	
New Well	Deepening X A	Alteration (repair/recondition	n) Abandonment				
(3) DRILL ME	THOD:	,		(10) STATIC WATE	R LEVEL: elow land surface.	Date	
Rotary Air	Rotary Mud	X Cable	Auger	Artesian pressure		square inch. Date	
Other				(11) WATER BEAR	ING ZONES:		
(4) PROPOSE	D USE:			Depth at which water			
Domestic Community Industrial X Irrigation							
Thermal	Injection	Livestock	Other	From	То	Estimated Flow Rate	SWL
(5) BORE HO	LE CONSTRUC	CTION:					
		s X No Depth of Comp					
Explosives used \	Yes X No Ty	/peAr	nount				
Diameter From	To Mater		1	(12) WELL LOG:	0		
					Ground ele	evation	
					Material	From To	SWL
				Installed 8" pipe s slot size - test pun	ize stainless steel	screen - 40,000	
				stopped the water		cieen out -	
How was seal place	ced: Method [] A	B C D	T F				
Other		NUMBER 110 MARI A MONTO			1 - 4 - · · · · · · · · · · · · · · · · ·		
Backfill placed from	m ft. to				The state of the s		
Gravel placed from	n ft. to	ft. Size of gravel					
Casing: Liner: Final location of st		Gauge Steel Plastic	Welded Threaded		RE	CEIVED	
******		NC.			nr	T 2 3 2001	
Perforatio	TIONS/SCREE	NO:			<u>U</u> L	. 1 / 4 / 2001	
Screens	Type	Material	· · · · · · · · · · · · · · · · · · ·			RESOURCES DEPT.	
F	Slot	Tele/pipe		The state of the s	3A	LEM, OREGON	
From To	size Number	Diameter size	Casing Liner				
				Date started 8/6/01		9/22/01	
						oleted 9/22/01	
				(unbonded) Water We		fication: ction, alteration, or abando	nment
/8\WELL TES	TC: Minimum (testing time is 1 ho	Carlo and Common	of this well is in complian	ce with Oregon water su	pply well construction stan	ndards.
Pump	Bailer	Air	Flowing	Materials used and inform belief.	nation reported above are	e true to my best knowledg	je and
Yield gal/min	Drawdown	Drill stem at	Artesian Time	9 (2)		WWC Number	
		J German	. 1110	O'Brico	*****	Date	
				performed on this well du	or the construction, alterating the construction date	ation, or abandonment wo	
Temperature of Was a water analy	/	Depth Artesian Flow found		performed during this time			
Did any strata cont		By whom le for intended use? Colored Other		Signed Signed	CU	best of my knowledge and WWC Number 66 Date 10/19/0	3
Depth of strata:				AMERICANY	ELL DRILLING		