

MARI 62339

R. Stadel & Sons Well & Pump Inc. 4385 Stadel Lane NE Silverton, OR 97381

STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

WELL I.D. # L 96428

START CARD # 200201

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Name Ellen Snow Well Number Address 12323 Hobart Rd. NE City Silverton State OR Zip 97381

(2) TYPE OF WORK [X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment [ ] Conversion

(3) DRILL METHOD [X] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger [ ] Cable Mud [ ] Other

(4) PROPOSED USE [ ] Domestic [ ] Community [ ] Industrial [X] Irrigation [ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION Special Construction: [ ] Yes [X] No Depth of Completed Well 157.5 ft. Explosives used: [ ] Yes [X] No Type Amount

Table with columns: BORE HOLE (Diameter, From, To), SEAL (Material, From, To), Sacks or Pounds. Rows include Bentonite and Cement seal data.

How was seal placed: Method [ ] A [ ] B [X] C [ ] D [ ] E [X] Other Bentonite placed dry Backfill placed from 65 ft. to 68 ft. Material sand Gravel placed from 0 ft. to 157.5 ft. Size of gravel 6/9 & 8/12

(6) CASING/LINER Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Rows for Casing and Liner.

Drive Shoe used [ ] Inside [X] Outside [ ] None Final location of shoe(s) 8" @ 157.5 cut off

(7) PERFORATIONS/SCREENS [ ] Perforations [X] Screens Method Type V-wire Material stainless

Table with columns: From, To, Slot Size, Number, Diameter, Tele/pipe size, Casing, Liner. Rows for perforation data.

(8) WELL TESTS: Minimum testing time is 1 hour [X] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian Yield gal/min 200 Drawdown 37' Drill stem at 6 hr. Time

Temperature of water 52 Depth Artesian Flow Found Was a water analysis done? [ ] Yes [ ] No By whom Did any strata contain water not suitable for intended use? [ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other Depth of strata: MAR 06 2009

(9) LOCATION OF WELL (legal description) County Marion Tax Lot 1200 Lot Township 6 S Range 1 W WM Section 21 SE 1/4 SE 1/4 Lat Long

Street Address of Well (or nearest address) 12323 Hobart Rd. NE Silverton, OR 97381

(10) STATIC WATER LEVEL 36.8 ft. below land surface. Date 2-13-09 Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES Table with columns: From, To, Estimated Flow Rate, SWL. Rows for water bearing zones.

(12) WELL LOG Table with columns: Soil, Material, From, To, SWL. Rows for well log details.

Date Started 1-9-09 Completed 2-12-09

(unbonded) Water Well Constructor Certification I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.

WWC Number 1358 Date 3-4-09 Signed [Signature]

(bonded) Water Well Constructor Certification I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above.

WWC Number 689 Date 3-4-09 Signed [Signature]

