

STATE OF OREGON WATER SUPPLY WELL REPORT

MARI 72116

WELL I.D. LABEL# L 158763 START CARD # 1080877 ORIGINAL LOG #

5/1/2026

(as required by ORS 537.545 & 537.765 and OAR 690-205-0210)

(1) LAND OWNER Owner Well I.D. First Name Last Name Company GOLDEN VALLEY FARMS Address 7385 HOWELL PRAIRIE RD NE City SILVERTON State OR Zip 97381

(2) TYPE OF WORK [X] New Well [] Deepening [] Conversion [] Alteration (complete 2a & 10) [] Abandonment (complete 5a)

(2a) PRE-ALTERATION Dia + From To Gauge Stl Plstc Wld Thrd Casing: Seal:

(3) DRILL METHOD [] Rotary Air [] Rotary Mud [X] Cable [] Auger [] Reverse Rotary [] Other

(4) PROPOSED USE [] Domestic [X] Irrigation [] Community [] Industrial/ Commercial [] Livestock [] Dewatering [] Thermal [] Injection [] Other

(5) BORE HOLE CONSTRUCTION Special Standard [] (Attach copy) Depth of Completed Well 245.00 ft.

Table with columns: Dia, From, To, Material, From, To, Amt, sacks/lbs. Rows for BORE HOLE and SEAL.

Seal placement method: [] A [] B [X] C [] D [] E [] Other: Backfill placed from 114 ft. to 245 ft. Material PEA ROCK Size 3/8

(5a) ABANDONMENT USING UNHYDRATED BENTONITE Proposed Amount Actual Amount

(6) CASING/LINER Table with columns: C/L, Dia, +, From, To, Gauge, Mat. Type, Wld, Thrd, Shoe, Location. Rows for C, L, L.

Temp casing [X] Yes Dia 20 From + [X] 1 To 39

(7) PERFORATIONS/SCREENS Perforations Method Screens Type V-Wire Material Stainless Steel Perf/ Casing/ Screen Screen Liner Dia From To Scrn/slot width length slots # of Tele/ Pipe size

(8) WELL TESTS: Minimum testing time is 1 hour

Table with columns: Type of Test, Yield (gal/min), Drawdown, Drill Stem/ Pump Depth, Duration (hr). Row for Pump.

Temperature 54 °F Lab analysis [] Yes By Water quality concerns? [] Yes (describe below) TDS amount 90 ppm From To Description Amount Units

(9) LOCATION OF WELL (legal description) County MARION Twp 6.00 S N/S Range 3.00 W E/W WM Sec 1 NW 1/4 of the SE 1/4 Tax Lot 100

(10) STATIC WATER LEVEL Date SWL(psi) + SWL(ft) Existing Well / Pre-Alteration Completed Well 4/23/2026 [X] 6

WATER BEARING ZONES Depth water was first found 17.00 SWL Date From To Est Flow SWL(psi) + SWL(ft)

(11) WELL LOG Ground Elevation 121.06 FT Material From To Soil Brown 0 3 Silt Brown 3 17 Silt Brown Sandy 17 21

(unbonded) Water Well Constructor Certification I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.

Signed Date License Number Date

(bonded) Water Well Constructor Certification I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above.

Signed DANIEL STADELI (E-filed) Drilling Company: Westerberg Drilling, Inc. License Number 1487 Date 5/1/2026

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

MARI 72116

5/1/2026

Map of Hole

