APR 27 1989

STATE OF OREGON

WATER WELL REPORT

WATER RESOURCES DEPT.

MIRI 88/2 /14/20ba
10560

(as required by ORS 537.765) (START CARD) # <u>10668</u> SALEM, OREGON (9) LOCATION OF WELL by legal description: (1) OWNER: Well Number:_ Delbert Hendricks County Marion Latitude ____ Longitude Address 11228 Silver Falls Hwy N or S, Range Zip 97325 *Aumsville* NE _ 14 _ NW (2) TYPE OF WORK: Block ____ Subdivision. Z Deepen Street Address of Well (or nearest address) Same as mailing ☐ New Well ☐ Recondition Abandon A (3) DRILL METHOD Rotary Air ☐ Rotary Mud ☐ Cable (10) STATIC WATER LEVEL: Other ___ ft. below land surface. (4) PROPOSED USE: Artesian pressure _ lb. per square inch. ☐ Community ☐ Domestic ☐ Industrial Irrigation (11) WATER BEARING ZONES: Other ☐ Thermal ☐ Injection Depth at which water was first found N/A(5) BORE HOLE CONSTRUCTION: Depth of Completed Well 600' ft. From Estimated Flow Rate SWL Yes Special Construction approval No Yes Explosives used Туре _ Amount No Water Endountered HOLE SEAL Amount Diameter From From sacks or pounds (12) WELL LOG: Ground elevation SWL Material From 375 Basalt grey hard □с \square D How was seal placed: Method 475 Reamed 6-8" Other _ 600 Basalt grey hard Backfill placed from ft. Gravel placed from ft. to ft. Size of gravel (6) CASING/LINER: Reamed 6-8" from 375 475 Welded Threaded Gauge | Steel Plastic 475 To Drilled new hole 600 Casing: O П Final location of shoe(s) (7) PERFORATIONS/SCREENS: Perforations Method ☐ Screen Material Pele/pipe From Number Diametel Casing Line 4-20-89 Date started Completed (unbonded) Water Well Constructor Certification: (8) WELL TESTS: Minimum testing time is 1 hour I certify that the work I performed on the construction, alteration, or Flowing Artesian abandonment of this well is in compliance with Oregon well construction ☐ Pump ☐ Bailer X Air standards. Materials used and information reported above are true to my best knowledge and belief. Yield gal/min Drawdown Drill stem at Time 100+ 5xhr. 600 Signed (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment Depth Artesian Flow Found work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well Yes. By whom Was a water analysis done? construction standards. This report is true to the best of my knowledge and Did any strata contain water not suitable for intended use? Too little belief. ☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other WWC Number Signed Date