**STATE OF OREGON**
**WATER SUPPLY WELL REPORT**
(as required by ORS 537.765 & OAR 690-205-0210)

**MORR 52600**

**7/6/2021**

**WELL I.D. LABEL# L** 101703
**START CARD #** 1052478
**ORIGINAL LOG #** MORROW 51844

## (1) LAND OWNER

Owner Well I.D. _____

First Name _____ Last Name _____
Company OREGON TRAVEL INFO COUNCIL
Address 1500 LIBERTY ST SE SUITE 150
City SALEM   State OR   Zip 97301

## (2) TYPE OF WORK

[ ] New Well   [X] Deepening   [ ] Conversion
[ ] Alteration (complete 2a & 10)   [ ] Abandonment(complete 5a)

## (2a) PRE-ALTERATION

| | Dia | + | From | To | Gauge | Stl | Plstc | Wld | Thrd |
|---|---|---|---|---|---|---|---|---|---|
| **Casing:** | 8 | [X] | 1 | 39 | .250 | (●) | ( ) | [X] | [ ] |

| | Material | From | To | Amt | sacks/lbs |
|---|---|---|---|---|---|
| **Seal:** | Bentonite | 0 | 18 | 16 | Sacks |

## (3) DRILL METHOD

[X] Rotary Air   [ ] Rotary Mud   [ ] Cable   [ ] Auger   [ ] Cable Mud
[ ] Reverse Rotary   [ ] Other _____

## (4) PROPOSED USE

[ ] Domestic   [ ] Irrigation   [X] Community
[ ] Industrial/ Commericial   [ ] Livestock   [ ] Dewatering
[ ] Thermal   [ ] Injection   [ ] Other _____

## (5) BORE HOLE CONSTRUCTION

Special Standard [ ] (Attach copy)
Depth of Completed Well 300.00 ft.

| BORE HOLE | | | SEAL | | | | sacks/lbs |
|---|---|---|---|---|---|---|---|
| Dia | From | To | Material | From | To | Amt | |
| 8 | 0 | 166 | Cement | 24 | 166 | 20 | S |
| 6 | 166 | 300 | | | Calculated | 14.75 | |
| | | | | | Calculated | | |

How was seal placed: Method [ ] A [X] B [ ] C [ ] D [ ] E
[ ] Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Filter pack from _____ ft. to _____ ft. Material _____ Size _____
Explosives used: [ ] Yes Type _____ Amount _____

## (5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount _____   Actual Amount _____

## (6) CASING/LINER

| Casing | Liner | Dia | + | From | To | Gauge | Stl | Plstc | Wld | Thrd |
|---|---|---|---|---|---|---|---|---|---|---|
| (●) | ( ) | 6 | [ ] | 26 | 166 | .250 | (●) | ( ) | [X] | [ ] |
| ( ) | ( ) | | | | | | ( ) | ( ) | | |
| ( ) | ( ) | | | | | | ( ) | ( ) | | |
| ( ) | ( ) | | | | | | ( ) | ( ) | | |
| ( ) | ( ) | | | | | | ( ) | ( ) | | |
| ( ) | ( ) | | | | | | ( ) | ( ) | | |

Shoe [ ] Inside [X] Outside [ ] Other   Location of shoe(s) 26
Temp casing [ ] Yes Dia _____ From + [ ] _____ To _____

## (7) PERFORATIONS/SCREENS

Perforations Method _____
Screens Type _____   Material _____

| Perf/Screen | Casing/Liner | Screen Dia | From | To | Scrn/slot width | Slot length | # of slots | Tele/pipe size |
|---|---|---|---|---|---|---|---|---|
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

## (8) WELL TESTS: Minimum testing time is 1 hour

( ) Pump   ( ) Bailer   (●) Air   ( ) Flowing Artesian

| Yield gal/min | Drawdown | Drill stem/Pump depth | Duration (hr) |
|---|---|---|---|
| 50 | | 300 | 1 |
| | | | |
| | | | |

Temperature 68 °F   Lab analysis [ ] Yes By _____
Water quality concerns? [ ] Yes (describe below)   TDS amount 229 ppm

| From | To | Description | Amount | Units |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |

## (9) LOCATION OF WELL (legal description)

County MORROW   Twp 4.00 N N/S   Range 24.00 E E/W WM
Sec 13 SW 1/4 of the NW 1/4   Tax Lot 300
Tax Map Number _____   Lot _____
Lat ___°___'___" or _____ DMS or DD
Long ___°___'___" or _____ DMS or DD
(●) Street address of well   ( ) Nearest address

MILE MARKER 161 I-84 EAST BOARDMAN

## (10) STATIC WATER LEVEL

| | Date | SWL(psi) | + | SWL(ft) |
|---|---|---|---|---|
| Existing Well / Pre-Alteration | 6/15/2021 | | | 34 |
| Completed Well | 6/23/2021 | | | 22 |

Flowing Artesian? [ ]   Dry Hole? [ ]

WATER BEARING ZONES   Depth water was first found 290.00

| SWL Date | From | To | Est Flow | SWL(psi) | + | SWL(ft) |
|---|---|---|---|---|---|---|
| 6/23/2021 | 290 | 295 | 50 | | | 22 |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

## (11) WELL LOG

Ground Elevation _____

| Material | From | To |
|---|---|---|
| EXISTING HOLE | 0 | 166 |
| BLACK BASALT | 166 | 290 |
| FRACTURED BLACK BASALT WITH | 290 | 295 |
| GREY CLAYSTONE | 290 | 295 |
| BLACK BASALT | 295 | 300 |
| | | |
| | | |

Date Started 6/15/2021   Completed 6/23/2021

**(unbonded) Water Well Constructor Certification**

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number 1985   Date 7/6/2021
Signed ALEXANDER SIMONTON (E-filed)

**(bonded) Water Well Constructor Certification**

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1881   Date 7/6/2021
Signed GARRY ZOLLMAN (E-filed)
Contact Info (optional) GARRY ZOLLMAN

ORIGINAL - WATER RESOURCES DEPARTMENT
THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK   Form Version: