| ORIGINAL File Original and | | ELL REPORT | -3 4N | 127 - | 32 A (|
|--|---|---|--|---------------|-------------|
| Duplicate with the STATE ENGINEER, SALEM, OREGON | ~ ') L IUN / | OF OREGON | State Well No | TOPE G | 72 |
| (1) OWNER: | (11) WELL TESTS: Drawdown is amount water level is lowered below static level | | | | |
| Address Histo | | Was a pump test made? X Yield: 960 gal./m: | | hom?んろ | iller |
| (2) LOCATION OF WELL: | | " | 21 | TO WIT GILLET | nrs. |
| County May-e V Owner's number, if any- | | Bailer test gal./mir | n. with ft. drawd | own after | " hrs. |
| NE 4 NE 4 Section 32 T. Bearing and distance from section or subdivisi | 4N R. 278 W.M. | | g.p.m. Date | | |
| 225'5 4 1145" | W Syby | (12) WELL LOG: | Was a chemical analysis | F 2 | Yes X No |
| ME COMMON SOU JS | | Depth drilled 106 | Diameter of well ft. Depth of completed | | inches. |
| | | Formation: Describe by col show thickness of aquifers stratum penetrated, with at | or, character, size of mate | rial and stri | ucture, and |
| TYPE OF WORK (check): | | MATE | | FROM | то |
| Well Deepening Reconditioning Abandon R | | and | | 35 | 38 |
| sandonment, describe material and procedu | ure in Item 11. | clay | | 100 | 106 |
| | (5) TYPE OF WELL: | | 11.00 | | |
| mestic Industrial Municipal tion Test Well Other | Rotary Driven Cable Jetted Dug Bored | | | | |
| CASING INSTALLED: Thr | | | | - | |
| | | | | | |
| "Diam. from | | | - | | |
| (7) DEDEOD ATTONY | | | | | |
| Type of perforator used Slate | | | - | | |
| SIZE of perforations in. by perforations from | 8 in. ft. to 95 ft. | | | | |
| perforations from | ft. toft. | | | | |
| perforations fromperforations from | | | | | |
| perforations from | | | | | |
| 3) SCREENS: Well screen ins | stalled Yes No | | Control of the Contro | | |
| Manufacturer's Name | | - " | | - | |
| Diam. Slot size Set from | ft. to ft | | and the second of the second o | | |
| iam Slot size Set from | ft. to ft. | Work started Prov 9 | 19 56 Completed | ec/10 | 1956 |
| (9) CONSTRUCTION: | | (13) PUMP: | 4 ! | | |
| | | Manufacturer's Name | arthington | | |
| Was a surface seal provided? X Yes No To what depth? | | Type: Murbon H.P. 50 | | | |
| Did any strata contain unusable water? Yes No | | Well Driller's Statement: | | _ | |
| Type of water? Septi Depth of strata 4 | | This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief. | | | |
| Line Line Line Line Line Line Line Line | | NAME Marion Duft | | | |
| Static level 66 ft. below land surface Date | | Address Rousewell Wash | | | |
| Artesian pressure lbs. per square | Driller's well number | · · · · · · · · · · · · · · · · · · · | *************************************** | | |
| Signed! The Man De Market 1 | | [Signed] | (Well Driller) | | |
| (Owner) | 19 19 | License No. 145 | Date H | 611, | 19.57 |